

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
Target Air Quality Levels													
EPA Site Specific Trigger Levels													
ASBESTOS-ST1-3/28/07	030709701-0001	Southwest Area (sidewalk bridge level)	3/28/07	1	3.090	Asbestos	PCME	EMSL	3/29/07	< 0.00080	No	No	
ASBESTOS-ST2-3/28/07	030709701-0002	Southeast Area (sidewalk bridge level)	3/28/07	1	2.970	Asbestos	PCME	EMSL	3/29/07	< 0.00083	No	No	
ASBESTOS-ST4-3/28/07	030709701-0003	Northwest Area (street-level)	3/28/07	1	3.000	Asbestos	PCME	EMSL	3/29/07	< 0.00082	No	No	
ASBESTOS-ST5-3/28/07	030709701-0004	Firehouse #10 (roof level)	3/28/07	1	3.020	Asbestos	PCME	EMSL	3/29/07	< 0.00082	No	No	
ASBESTOS-ST10-3/28/07	030709701-0005	North Side Sidewalk Bridge	3/28/07	1	3.020	Asbestos	PCME	EMSL	3/29/07	< 0.00082	No	No	
ASBESTOS-ST11-3/28/07	030709701-0006	90 Trinity Place (roof level)	3/28/07	1	2.920	Asbestos	PCME	EMSL	3/29/07	< 0.00085	No	No	
ASBESTOS-ST12-3/28/07	030709701-0007	110 Greenwich Street (roof level)	3/28/07	1	2.990	Asbestos	PCME	EMSL	3/29/07	< 0.00083	No	No	
ASBESTOS-ST13-3/28/07	030709701-0008	Marriott Hotel, 38th Floor (roof level)	3/28/07	1	3.020	Asbestos	PCME	EMSL	3/29/07	< 0.00082	No	No	
ASBESTOS-ST14-3/28/07	030709701-0009	West Face - South end at corner (scaffolding level)	3/28/07	1	3.040	Asbestos	PCME	EMSL	3/29/07	< 0.00081	No	No	
ASBESTOS-ST15-3/28/07	030709701-0010	South Face - East end at corner (scaffolding level)	3/28/07	1	3.030	Asbestos	PCME	EMSL	3/29/07	< 0.00081	No	No	
ASBESTOS-ST16-3/28/07	030709701-0011	East Face - North end at corner (scaffolding level)	3/28/07	1	3.020	Asbestos	PCME	EMSL	3/29/07	< 0.00082	No	No	
ASBESTOS-ST17-3/28/07	030709701-0012	North Face - West end at corner (scaffolding level)	3/28/07	1	3.040	Asbestos	PCME	EMSL	3/29/07	< 0.00081	No	No	
ASBESTOS-ST1-3/29/07	030709832-0001	Southwest Area (sidewalk bridge level)	3/29/07	1	3.090	Asbestos	PCME	EMSL	3/30/07	< 0.00080	No	No	
ASBESTOS-ST2-3/29/07	030709832-0002	Southeast Area (sidewalk bridge level)	3/29/07	1	3.090	Asbestos	PCME	EMSL	3/30/07	< 0.00080	No	No	
ASBESTOS-ST4-3/29/07	030709832-0003	Northwest Area (street-level)	3/29/07	1	2.890	Asbestos	PCME	EMSL	3/30/07	< 0.00079	No	No	
ASBESTOS-ST5-3/29/07	030709832-0004	Firehouse #10 (roof level)	3/29/07	1	3.040	Asbestos	PCME	EMSL	3/30/07	< 0.00081	No	No	
ASBESTOS-ST10-3/29/07	030709832-0005	North Side Sidewalk Bridge	3/29/07	1	2.970	Asbestos	PCME	EMSL	3/30/07	< 0.00083	No	No	
ASBESTOS-ST11-3/29/07	030709832-0006	90 Trinity Place (roof level)	3/29/07	1	3.280	Asbestos	PCME	EMSL	3/30/07	< 0.00075	No	No	
ASBESTOS-ST12-3/29/07	030709832-0007	110 Greenwich Street (roof level)	3/29/07	1	2.990	Asbestos	PCME	EMSL	3/30/07	< 0.00083	No	No	
ASBESTOS-ST13-3/29/07	030709832-0008	Marriott Hotel, 38th Floor (roof level)	3/29/07	1	3.020	Asbestos	PCME	EMSL	3/30/07	< 0.00082	No	No	
ASBESTOS-ST14-3/29/07	030709832-0009	West Face - South end at corner (scaffolding level)	3/29/07	1	3.040	Asbestos	PCME	EMSL	3/30/07	< 0.00081	No	No	
ASBESTOS-ST15-3/29/07	030709832-0010	South Face - East end at corner (scaffolding level)	3/29/07	1	3.020	Asbestos	PCME	EMSL	3/30/07	< 0.00082	No	No	
ASBESTOS-ST16-3/29/07	030709832-0011	East Face - North end at corner (scaffolding level)	3/29/07	1	3.040	Asbestos	PCME	EMSL	3/30/07	< 0.00081	No	No	
ASBESTOS-ST17-3/29/07	030709832-0012	North Face - West end at corner (scaffolding level)	3/29/07	1	3.010	Asbestos	PCME	EMSL	3/30/07	< 0.00082	No	No	