

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
<b>Target Air Quality Levels</b>													
<b>EPA Site Specific Trigger Levels</b>													
ASBESTOS-ST1-4/09/07	030710965-0001	Southwest Area (sidewalk bridge level)	4/9/07	1	3.060	Asbestos	PCME	EMSL	4/10/07	< 0.00081	No	No	
ASBESTOS-ST2-4/09/07	030710965-0002	Southeast Area (sidewalk bridge level)	4/9/07	1	2.990	Asbestos	PCME	EMSL	4/10/07	< 0.00083	No	No	
ASBESTOS-ST4-4/09/07	030710965-0003	Northwest Area (street-level)	4/9/07	1	2.950	Asbestos	PCME	EMSL	4/10/07	< 0.00084	No	No	
ASBESTOS-ST5-4/09/07	030710965-0004	Firehouse #10 (roof level)	4/9/07	1	3.020	Asbestos	PCME	EMSL	4/10/07	< 0.00082	No	No	
ASBESTOS-ST10-4/09/07	030710965-0005	North Side Sidewalk Bridge	4/9/07	1	3.220	Asbestos	PCME	EMSL	4/10/07	< 0.00077	No	No	
ASBESTOS-ST11-4/09/07	030710965-0006	90 Trinity Place (roof level)	4/9/07	1	3.090	Asbestos	PCME	EMSL	4/10/07	< 0.00080	No	No	
ASBESTOS-ST12-4/09/07	030710965-0007	110 Greenwich Street (roof level)	4/9/07	1	2.990	Asbestos	PCME	EMSL	4/10/07	< 0.00083	No	No	
ASBESTOS-ST13-4/09/07	030710965-0008	Marriott Hotel, 38th Floor (roof level)	4/9/07	1	3.040	Asbestos	PCME	EMSL	4/10/07	< 0.00081	No	No	
ASBESTOS-ST14-4/09/07	030710965-0009	West Face - South end at corner (scaffolding level)	4/9/07	1	3.000	Asbestos	PCME	EMSL	4/10/07	< 0.00082	No	No	
ASBESTOS-ST15-4/09/07	030710965-0010	South Face - East end at corner (scaffolding level)	4/9/07	1	3.020	Asbestos	PCME	EMSL	4/10/07	< 0.00082	No	No	
ASBESTOS-ST16-4/09/07	030710965-0011	East Face - North end at corner (scaffolding level)	4/9/07	1	3.040	Asbestos	PCME	EMSL	4/10/07	< 0.00081	No	No	
ASBESTOS-ST17-4/09/07	030710965-0012	North Face - West end at corner (scaffolding level)	4/9/07	1	3.090	Asbestos	PCME	EMSL	4/10/07	< 0.00080	No	No	
ASBESTOS-ST1-4/10/07	030711071-0001	Southwest Area (sidewalk bridge level)	4/10/07	1	3.030	Asbestos	PCME	EMSL	4/11/07	< 0.00081	No	No	
ASBESTOS-ST2-4/10/07	030711071-0002	Southeast Area (sidewalk bridge level)	4/10/07	1	3.060	Asbestos	PCME	EMSL	4/11/07	< 0.00081	No	No	
ASBESTOS-ST4-4/10/07	030711071-0003	Northwest Area (street-level)	4/10/07	1	3.120	Asbestos	PCME	EMSL	4/11/07	< 0.00079	No	No	
ASBESTOS-ST5-4/10/07	030711071-0004	Firehouse #10 (roof level)	4/10/07	1	3.030	Asbestos	PCME	EMSL	4/11/07	< 0.00081	No	No	
ASBESTOS-ST10-4/10/07	030711071-0005	North Side Sidewalk Bridge	4/10/07	1	3.030	Asbestos	PCME	EMSL	4/11/07	< 0.00081	No	No	
ASBESTOS-ST11-4/10/07	030711071-0006	90 Trinity Place (roof level)	4/10/07	1	2.780	Asbestos	PCME	EMSL	4/11/07	< 0.00089	No	No	
ASBESTOS-ST12-4/10/07	030711071-0007	110 Greenwich Street (roof level)	4/10/07	1	3.020	Asbestos	PCME	EMSL	4/11/07	< 0.00082	No	No	
ASBESTOS-ST13-4/10/07	030711071-0008	Marriott Hotel, 38th Floor (roof level)	4/10/07	1	3.010	Asbestos	PCME	EMSL	4/11/07	< 0.00082	No	No	
ASBESTOS-ST14-4/10/07	030711071-0009	West Face - South end at corner (scaffolding level)	4/10/07	1	3.010	Asbestos	PCME	EMSL	4/11/07	< 0.00082	No	No	
ASBESTOS-ST15-4/10/07	030711071-0010	South Face - East end at corner (scaffolding level)	4/10/07	1	3.000	Asbestos	PCME	EMSL	4/11/07	< 0.00082	No	No	
ASBESTOS-ST16-4/10/07	030711071-0011	East Face - North end at corner (scaffolding level)	4/10/07	1	3.050	Asbestos	PCME	EMSL	4/11/07	< 0.00081	No	No	
ASBESTOS-ST17-4/10/07	030711071-0012	North Face - West end at corner (scaffolding level)	4/10/07	1	3.030	Asbestos	PCME	EMSL	4/11/07	< 0.00081	No	No	