

| TRC Field Sample No. | Sample No. | Sampling Location | Collection Start Date | Work Shift | Sample Volume (m ³) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Asbestos PCME Concentration (f/cm3) | Exceeds Target Air Quality Levels | Exceeds EPA Site Specific Trigger Levels | Comments |
|----------------------------------|----------------|---|-----------------------|------------|---------------------------------|----------|-------------------|------|-------------------------|-------------------------------------|-----------------------------------|--|----------|
| Target Air Quality Levels | | | | | | | | | | 0.0009 | | | |
| EPA Site Specific Trigger Levels | | | | | | | | | | NA | | | |
| ASBESTOS-ST1-4/18/08 | 030811598-0001 | Southwest Area (sidewalk bridge level) | 4/18/08 | 1 | 3.050 | Asbestos | PCME | EMSL | 4/20/08 | < 0.00081 | No | No | |
| ASBESTOS-ST2-4/18/08 | 030811598-0002 | Southeast Area (sidewalk bridge level) | 4/18/08 | 1 | 3.070 | Asbestos | PCME | EMSL | 4/20/08 | < 0.00080 | No | No | |
| ASBESTOS-ST4-4/18/08 | 030811598-0003 | Northwest Area (street-level) | 4/18/08 | 1 | 2.990 | Asbestos | PCME | EMSL | 4/20/08 | < 0.00083 | No | No | |
| ASBESTOS-ST5-4/18/08 | 030811598-0004 | Firehouse #10 (roof level) | 4/18/08 | 1 | 3.110 | Asbestos | PCME | EMSL | 4/20/08 | < 0.00079 | No | No | |
| ASBESTOS-ST10-4/18/08 | 030811598-0005 | North Side Sidewalk Bridge | 4/18/08 | 1 | 3.060 | Asbestos | PCME | EMSL | 4/20/08 | < 0.00081 | No | No | |
| ASBESTOS-ST11-4/18/08 | 030811598-0006 | 90 Trinity Place (roof level) | 4/18/08 | 1 | 3.040 | Asbestos | PCME | EMSL | 4/20/08 | < 0.00081 | No | No | |
| ASBESTOS-ST12-4/18/08 | 030811598-0007 | 110 Greenwich Street (roof level) | 4/18/08 | 1 | 3.040 | Asbestos | PCME | EMSL | 4/20/08 | < 0.00081 | No | No | |
| ASBESTOS-ST13-4/18/08 | 030811598-0008 | Marriott Hotel, 38th Floor (roof level) | 4/18/08 | 1 | 3.090 | Asbestos | PCME | EMSL | 4/20/08 | < 0.00080 | No | No | |
| ASBESTOS-ST14-4/18/08 | 030811598-0009 | West Face - South end at corner (scaffolding level) | 4/18/08 | 1 | 3.060 | Asbestos | PCME | EMSL | 4/20/08 | < 0.00081 | No | No | |
| ASBESTOS-ST15-4/18/08 | 030811598-0010 | South Face - East end at corner (scaffolding level) | 4/18/08 | 1 | 3.040 | Asbestos | PCME | EMSL | 4/20/08 | < 0.00081 | No | No | |
| ASBESTOS-ST16-4/18/08 | 030811598-0011 | East Face - North end at corner (scaffolding level) | 4/18/08 | 1 | 3.060 | Asbestos | PCME | EMSL | 4/20/08 | < 0.00081 | No | No | |
| ASBESTOS-ST17-4/18/08 | 030811598-0012 | North Face - West end at corner (scaffolding level) | 4/18/08 | 1 | 3.060 | Asbestos | PCME | EMSL | 4/20/08 | < 0.00081 | No | No | |
| ASBESTOS-ST1-4/19/08 | 030811711-0001 | Southwest Area (sidewalk bridge level) | 4/19/08 | 1 | 3.070 | Asbestos | PCME | EMSL | 4/21/08 | < 0.00080 | No | No | |
| ASBESTOS-ST2-4/19/08 | 030811711-0002 | Southeast Area (sidewalk bridge level) | 4/19/08 | 1 | 3.010 | Asbestos | PCME | EMSL | 4/21/08 | < 0.00082 | No | No | |
| ASBESTOS-ST4-4/19/08 | 030811711-0003 | Northwest Area (street-level) | 4/19/08 | 1 | 3.040 | Asbestos | PCME | EMSL | 4/21/08 | < 0.00081 | No | No | |
| ASBESTOS-ST5-4/19/08 | 030811711-0004 | Firehouse #10 (roof level) | 4/19/08 | 1 | 3.060 | Asbestos | PCME | EMSL | 4/21/08 | < 0.00081 | No | No | |
| ASBESTOS-ST10-4/19/08 | 030811711-0005 | North Side Sidewalk Bridge | 4/19/08 | 1 | 3.090 | Asbestos | PCME | EMSL | 4/21/08 | < 0.00080 | No | No | |
| ASBESTOS-ST11-4/19/08 | 030811711-0006 | 90 Trinity Place (roof level) | 4/19/08 | 1 | 3.040 | Asbestos | PCME | EMSL | 4/21/08 | < 0.00081 | No | No | |
| ASBESTOS-ST12-4/19/08 | 030811711-0007 | 110 Greenwich Street (roof level) | 4/19/08 | 1 | 3.010 | Asbestos | PCME | EMSL | 4/21/08 | < 0.00082 | No | No | |
| ASBESTOS-ST13-4/19/08 | 030811711-0008 | Marriott Hotel, 38th Floor (roof level) | 4/19/08 | 1 | 3.040 | Asbestos | PCME | EMSL | 4/21/08 | < 0.00081 | No | No | |
| ASBESTOS-ST14-4/19/08 | 030811711-0009 | West Face - South end at corner (scaffolding level) | 4/19/08 | 1 | 3.040 | Asbestos | PCME | EMSL | 4/21/08 | < 0.00081 | No | No | |
| ASBESTOS-ST15-4/19/08 | 030811711-0010 | South Face - East end at corner (scaffolding level) | 4/19/08 | 1 | 3.000 | Asbestos | PCME | EMSL | 4/21/08 | < 0.00082 | No | No | |
| ASBESTOS-ST16-4/19/08 | 030811711-0011 | East Face - North end at corner (scaffolding level) | 4/19/08 | 1 | 3.010 | Asbestos | PCME | EMSL | 4/21/08 | < 0.00082 | No | No | |
| ASBESTOS-ST17-4/19/08 | 030811711-0012 | North Face - West end at corner (scaffolding level) | 4/19/08 | 1 | 3.010 | Asbestos | PCME | EMSL | 4/21/08 | < 0.00082 | No | No | |
| ASBESTOS-ST1-4/20/08 | 030811710-0001 | Southwest Area (sidewalk bridge level) | 4/20/08 | 1 | 3.120 | Asbestos | PCME | EMSL | 4/21/08 | < 0.00079 | No | No | |
| ASBESTOS-ST2-4/20/08 | 030811710-0002 | Southeast Area (sidewalk bridge level) | 4/20/08 | 1 | 3.080 | Asbestos | PCME | EMSL | 4/21/08 | < 0.00080 | No | No | |
| ASBESTOS-ST4-4/20/08 | 030811710-0003 | Northwest Area (street-level) | 4/20/08 | 1 | 3.010 | Asbestos | PCME | EMSL | 4/21/08 | < 0.00082 | No | No | |
| ASBESTOS-ST5-4/20/08 | 030811710-0004 | Firehouse #10 (roof level) | 4/20/08 | 1 | 3.160 | Asbestos | PCME | EMSL | 4/21/08 | < 0.00078 | No | No | |
| ASBESTOS-ST10-4/20/08 | 030811710-0005 | North Side Sidewalk Bridge | 4/20/08 | 1 | 3.070 | Asbestos | PCME | EMSL | 4/21/08 | < 0.00080 | No | No | |
| ASBESTOS-ST11-4/20/08 | 030811710-0006 | 90 Trinity Place (roof level) | 4/20/08 | 1 | 3.420 | Asbestos | PCME | EMSL | 4/21/08 | < 0.00072 | No | No | |
| ASBESTOS-ST12-4/20/08 | 030811710-0007 | 110 Greenwich Street (roof level) | 4/20/08 | 1 | 3.060 | Asbestos | PCME | EMSL | 4/21/08 | < 0.00081 | No | No | |
| ASBESTOS-ST13-4/20/08 | 030811710-0008 | Marriott Hotel, 38th Floor (roof level) | 4/20/08 | 1 | 2.980 | Asbestos | PCME | EMSL | 4/21/08 | < 0.00083 | No | No | |
| ASBESTOS-ST14-4/20/08 | 030811710-0009 | West Face - South end at corner (scaffolding level) | 4/20/08 | 1 | 3.080 | Asbestos | PCME | EMSL | 4/21/08 | < 0.00080 | No | No | |
| ASBESTOS-ST15-4/20/08 | 030811710-0010 | South Face - East end at corner (scaffolding level) | 4/20/08 | 1 | 2.970 | Asbestos | PCME | EMSL | 4/21/08 | < 0.00083 | No | No | |
| ASBESTOS-ST16-4/20/08 | 030811710-0011 | East Face - North end at corner (scaffolding level) | 4/20/08 | 1 | 2.990 | Asbestos | PCME | EMSL | 4/21/08 | < 0.00083 | No | No | |
| ASBESTOS-ST17-4/20/08 | 030811710-0012 | North Face - West end at corner (scaffolding level) | 4/20/08 | 1 | 2.920 | Asbestos | PCME | EMSL | 4/21/08 | < 0.00085 | No | No | |