

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
										Target Air Quality Levels			
										EPA Site Specific Trigger Levels			
ASBESTOS-ST1-5/30/07	030717425-0001	Southwest Area (sidewalk bridge level)	5/30/07	1	3.040	Asbestos	PCME	EMSL	5/31/07	< 0.00081	No	No	
ASBESTOS-ST2-5/30/07	030717425-0002	Southeast Area (sidewalk bridge level)	5/30/07	1	3.070	Asbestos	PCME	EMSL	5/31/07	< 0.00080	No	No	
ASBESTOS-ST4-5/30/07	030717425-0003	Northwest Area (street-level)	5/30/07	1	3.060	Asbestos	PCME	EMSL	5/31/07	< 0.00081	No	No	
ASBESTOS-ST5-5/30/07	030717425-0004	Firehouse #10 (roof level)	5/30/07	1	3.020	Asbestos	PCME	EMSL	5/31/07	< 0.00082	No	No	
ASBESTOS-ST10-5/30/07	030717425-0005	North Side Sidewalk Bridge	5/30/07	1	3.060	Asbestos	PCME	EMSL	5/31/07	< 0.00081	No	No	
ASBESTOS-ST11-5/30/07	030717425-0006	90 Trinity Place (roof level)	5/30/07	1	3.020	Asbestos	PCME	EMSL	5/31/07	< 0.00082	No	No	
ASBESTOS-ST12-5/30/07	030717425-0007	110 Greenwich Street (roof level)	5/30/07	1	3.060	Asbestos	PCME	EMSL	5/31/07	< 0.00081	No	No	
ASBESTOS-ST13-5/30/07	030717425-0008	Marriott Hotel, 38th Floor (roof level)	5/30/07	1	3.020	Asbestos	PCME	EMSL	5/31/07	< 0.00082	No	No	
ASBESTOS-ST14-5/30/07	030717425-0009	West Face - South end at corner (scaffolding level)	5/30/07	1	3.010	Asbestos	PCME	EMSL	5/31/07	< 0.00082	No	No	
ASBESTOS-ST15-5/30/07	030717425-0010	South Face - East end at corner (scaffolding level)	5/30/07	1	3.010	Asbestos	PCME	EMSL	5/31/07	< 0.00082	No	No	
ASBESTOS-ST16-5/30/07	030717425-0011	East Face - North end at corner (scaffolding level)	5/30/07	1	3.060	Asbestos	PCME	EMSL	5/31/07	< 0.00081	No	No	
ASBESTOS-ST17-5/30/07	030717425-0012	North Face - West end at corner (scaffolding level)	5/30/07	1	2.970	Asbestos	PCME	EMSL	5/31/07	< 0.00083	No	No	
ASBESTOS-ST1-5/31/07	030717599-0001	Southwest Area (sidewalk bridge level)	5/31/07	1	3.040	Asbestos	PCME	EMSL	6/1/07	< 0.00081	No	No	
ASBESTOS-ST2-5/31/07	030717599-0002	Southeast Area (sidewalk bridge level)	5/31/07	1	3.060	Asbestos	PCME	EMSL	6/1/07	< 0.00081	No	No	
ASBESTOS-ST4-5/31/07	030717599-0003	Northwest Area (street-level)	5/31/07	1	3.050	Asbestos	PCME	EMSL	6/1/07	< 0.00081	No	No	
ASBESTOS-ST5-5/31/07	030717599-0004	Firehouse #10 (roof level)	5/31/07	1	3.020	Asbestos	PCME	EMSL	6/1/07	< 0.00082	No	No	
ASBESTOS-ST10-5/31/07	030717599-0005	North Side Sidewalk Bridge	5/31/07	1	3.020	Asbestos	PCME	EMSL	6/1/07	< 0.00082	No	No	
ASBESTOS-ST100-5/31/07	030717599-0013	Station 10 Field Duplicate	5/31/07	1	2.960	Asbestos	PCME	EMSL	6/1/07	< 0.00083	No	No	
ASBESTOS-ST11-5/31/07	030717599-0006	90 Trinity Place (roof level)	5/31/07	1	3.080	Asbestos	PCME	EMSL	6/1/07	< 0.00080	No	No	
ASBESTOS-ST12-5/31/07	030717599-0007	110 Greenwich Street (roof level)	5/31/07	1	3.030	Asbestos	PCME	EMSL	6/1/07	< 0.00081	No	No	
ASBESTOS-ST13-5/31/07	030717599-0008	Marriott Hotel, 38th Floor (roof level)	5/31/07	1	3.040	Asbestos	PCME	EMSL	6/1/07	< 0.00081	No	No	
ASBESTOS-ST14-5/31/07	030717599-0009	West Face - South end at corner (scaffolding level)	5/31/07	1	3.040	Asbestos	PCME	EMSL	6/1/07	< 0.00081	No	No	
ASBESTOS-ST15-5/31/07	030717599-0010	South Face - East end at corner (scaffolding level)	5/31/07	1	3.030	Asbestos	PCME	EMSL	6/1/07	< 0.00081	No	No	
ASBESTOS-ST16-5/31/07	030717599-0011	East Face - North end at corner (scaffolding level)	5/31/07	1	3.010	Asbestos	PCME	EMSL	6/1/07	< 0.00082	No	No	
ASBESTOS-ST17-5/31/07	030717599-0012	North Face - West end at corner (scaffolding level)	5/31/07	1	3.010	Asbestos	PCME	EMSL	6/1/07	< 0.00082	No	No	