

| TRC Field Sample No. | Sample No. | Sampling Location | Collection Start Date | Work Shift | Sample Volume (m ³) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Asbestos PCME Concentration (f/cm3) | Exceeds Target Air Quality Levels | Exceeds EPA Site Specific Trigger Levels | Comments |
|----------------------|----------------|---|-----------------------|------------|---------------------------------|----------|-------------------|------|-------------------------|-------------------------------------|-----------------------------------|--|----------|
| | | | | | | | | | | 0.0009 | | | |
| | | | | | | | | | | NA | | | |
| ASBESTOS-ST1-6/1/07 | 030717860-0001 | Southwest Area (sidewalk bridge level) | 6/1/07 | 1 | 2.970 | Asbestos | PCME | EMSL | 6/4/07 | < 0.00083 | No | No | |
| ASBESTOS-ST2-6/1/07 | 030717860-0002 | Southeast Area (sidewalk bridge level) | 6/1/07 | 1 | 3.030 | Asbestos | PCME | EMSL | 6/4/07 | < 0.00081 | No | No | |
| ASBESTOS-ST4-6/1/07 | 030717860-0003 | Northwest Area (street-level) | 6/1/07 | 1 | 3.040 | Asbestos | PCME | EMSL | 6/4/07 | < 0.00081 | No | No | |
| ASBESTOS-ST5-6/1/07 | 030717860-0004 | Firehouse #10 (roof level) | 6/1/07 | 1 | 3.010 | Asbestos | PCME | EMSL | 6/4/07 | < 0.00082 | No | No | |
| ASBESTOS-ST10-6/1/07 | 030717860-0005 | North Side Sidewalk Bridge | 6/1/07 | 1 | 3.010 | Asbestos | PCME | EMSL | 6/4/07 | < 0.00082 | No | No | |
| ASBESTOS-ST11-6/1/07 | 030717860-0006 | 90 Trinity Place (roof level) | 6/1/07 | 1 | 3.070 | Asbestos | PCME | EMSL | 6/4/07 | < 0.00080 | No | No | |
| ASBESTOS-ST12-6/1/07 | 030717860-0007 | 110 Greenwich Street (roof level) | 6/1/07 | 1 | 3.010 | Asbestos | PCME | EMSL | 6/4/07 | < 0.00082 | No | No | |
| ASBESTOS-ST13-6/1/07 | 030717860-0008 | Marriott Hotel, 38th Floor (roof level) | 6/1/07 | 1 | 3.090 | Asbestos | PCME | EMSL | 6/4/07 | < 0.00080 | No | No | |
| ASBESTOS-ST14-6/1/07 | 030717860-0009 | West Face - South end at corner (scaffolding level) | 6/1/07 | 1 | 3.010 | Asbestos | PCME | EMSL | 6/4/07 | < 0.00082 | No | No | |
| ASBESTOS-ST15-6/1/07 | 030717860-0010 | South Face - East end at corner (scaffolding level) | 6/1/07 | 1 | 3.020 | Asbestos | PCME | EMSL | 6/4/07 | < 0.00082 | No | No | |
| ASBESTOS-ST16-6/1/07 | 030717860-0011 | East Face - North end at corner (scaffolding level) | 6/1/07 | 1 | 3.010 | Asbestos | PCME | EMSL | 6/4/07 | < 0.00082 | No | No | |
| ASBESTOS-ST17-6/1/07 | 030717860-0012 | North Face - West end at corner (scaffolding level) | 6/1/07 | 1 | 3.010 | Asbestos | PCME | EMSL | 6/4/07 | < 0.00082 | No | No | |
| ASBESTOS-ST1-6/2/07 | 030717861-0001 | Southwest Area (sidewalk bridge level) | 6/2/07 | 1 | 3.350 | Asbestos | PCME | EMSL | 6/4/07 | < 0.00074 | No | No | |
| ASBESTOS-ST2-6/2/07 | 030717861-0002 | Southeast Area (sidewalk bridge level) | 6/2/07 | 1 | 3.070 | Asbestos | PCME | EMSL | 6/4/07 | < 0.00080 | No | No | |
| ASBESTOS-ST4-6/2/07 | 030717861-0003 | Northwest Area (street-level) | 6/2/07 | 1 | 2.940 | Asbestos | PCME | EMSL | 6/4/07 | < 0.00084 | No | No | |
| ASBESTOS-ST5-6/2/07 | 030717861-0004 | Firehouse #10 (roof level) | 6/2/07 | 1 | 3.040 | Asbestos | PCME | EMSL | 6/4/07 | < 0.00081 | No | No | |
| ASBESTOS-ST10-6/2/07 | 030717861-0005 | North Side Sidewalk Bridge | 6/2/07 | 1 | 3.010 | Asbestos | PCME | EMSL | 6/4/07 | < 0.00082 | No | No | |
| ASBESTOS-ST11-6/2/07 | 030717861-0006 | 90 Trinity Place (roof level) | 6/2/07 | 1 | 3.020 | Asbestos | PCME | EMSL | 6/4/07 | < 0.00082 | No | No | |
| ASBESTOS-ST12-6/2/07 | 030717861-0007 | 110 Greenwich Street (roof level) | 6/2/07 | 1 | 3.040 | Asbestos | PCME | EMSL | 6/4/07 | < 0.00081 | No | No | |
| ASBESTOS-ST13-6/2/07 | 030717861-0008 | Marriott Hotel, 38th Floor (roof level) | 6/2/07 | 1 | 3.020 | Asbestos | PCME | EMSL | 6/4/07 | < 0.00082 | No | No | |
| ASBESTOS-ST14-6/2/07 | 030717861-0009 | West Face - South end at corner (scaffolding level) | 6/2/07 | 1 | 3.040 | Asbestos | PCME | EMSL | 6/4/07 | < 0.00081 | No | No | |
| ASBESTOS-ST15-6/2/07 | 030717861-0010 | South Face - East end at corner (scaffolding level) | 6/2/07 | 1 | 3.040 | Asbestos | PCME | EMSL | 6/4/07 | < 0.00081 | No | No | |
| ASBESTOS-ST16-6/2/07 | 030717861-0011 | East Face - North end at corner (scaffolding level) | 6/2/07 | 1 | 3.020 | Asbestos | PCME | EMSL | 6/4/07 | < 0.00082 | No | No | |
| ASBESTOS-ST17-6/2/07 | 030717861-0012 | North Face - West end at corner (scaffolding level) | 6/2/07 | 1 | 3.020 | Asbestos | PCME | EMSL | 6/4/07 | < 0.00082 | No | No | |
| ASBESTOS-ST1-6/3/07 | 030717862-0001 | Southwest Area (sidewalk bridge level) | 6/3/07 | 1 | 2.960 | Asbestos | PCME | EMSL | 6/4/07 | < 0.00083 | No | No | |
| ASBESTOS-ST2-6/3/07 | 030717862-0002 | Southeast Area (sidewalk bridge level) | 6/3/07 | 1 | 3.070 | Asbestos | PCME | EMSL | 6/4/07 | < 0.00080 | No | No | |
| ASBESTOS-ST4-6/3/07 | 030717862-0003 | Northwest Area (street-level) | 6/3/07 | 1 | 2.990 | Asbestos | PCME | EMSL | 6/4/07 | < 0.00083 | No | No | |
| ASBESTOS-ST5-6/3/07 | 030717862-0004 | Firehouse #10 (roof level) | 6/3/07 | 1 | 3.060 | Asbestos | PCME | EMSL | 6/4/07 | < 0.00081 | No | No | |
| ASBESTOS-ST10-6/3/07 | 030717862-0005 | North Side Sidewalk Bridge | 6/3/07 | 1 | 3.010 | Asbestos | PCME | EMSL | 6/4/07 | < 0.00082 | No | No | |
| ASBESTOS-ST11-6/3/07 | 030717862-0006 | 90 Trinity Place (roof level) | 6/3/07 | 1 | 2.960 | Asbestos | PCME | EMSL | 6/4/07 | < 0.00083 | No | No | |
| ASBESTOS-ST12-6/3/07 | 030717862-0007 | 110 Greenwich Street (roof level) | 6/3/07 | 1 | 2.970 | Asbestos | PCME | EMSL | 6/4/07 | < 0.00083 | No | No | |
| ASBESTOS-ST13-6/3/07 | 030717862-0008 | Marriott Hotel, 38th Floor (roof level) | 6/3/07 | 1 | 3.010 | Asbestos | PCME | EMSL | 6/4/07 | < 0.00082 | No | No | |
| ASBESTOS-ST14-6/3/07 | 030717862-0009 | West Face - South end at corner (scaffolding level) | 6/3/07 | 1 | 3.080 | Asbestos | PCME | EMSL | 6/4/07 | < 0.00080 | No | No | |
| ASBESTOS-ST15-6/3/07 | 030717862-0010 | South Face - East end at corner (scaffolding level) | 6/3/07 | 1 | 3.040 | Asbestos | PCME | EMSL | 6/4/07 | < 0.00081 | No | No | |
| ASBESTOS-ST16-6/3/07 | 030717862-0011 | East Face - North end at corner (scaffolding level) | 6/3/07 | 1 | 3.000 | Asbestos | PCME | EMSL | 6/4/07 | < 0.00082 | No | No | |
| ASBESTOS-ST17-6/3/07 | 030717862-0012 | North Face - West end at corner (scaffolding level) | 6/3/07 | 1 | 3.030 | Asbestos | PCME | EMSL | 6/4/07 | < 0.00081 | No | No | |