

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments	
										0.0009	Air Quality Levels	Site Specific Trigger Levels		
										NA				
Target Air Quality Levels														
EPA Site Specific Trigger Levels														
ASBESTOS-ST1-7/10/06	030621166-0001	Southwest Area (sidewalk bridge level)	7/10/06	1	2.940	Asbestos	PCME	EMSL	7/11/06	< 0.00084	No	No		
ASBESTOS-ST2-7/10/06	030621166-0002	Southeast Area (sidewalk bridge level)	7/10/06	1	2.940	Asbestos	PCME	EMSL	7/11/06	< 0.00084	No	No		
ASBESTOS-ST4-7/10/06	030621166-0003	Northwest Area (street-level)	7/10/06	1	2.940	Asbestos	PCME	EMSL	7/11/06	< 0.00084	No	No		
ASBESTOS-ST5-7/10/06	030621166-0004	Firehouse #10 (roof level)	7/10/06	1	2.940	Asbestos	PCME	EMSL	7/11/06	< 0.00084	No	No		
ASBESTOS-ST6-7/10/06	030621169-0001	Southwest Area (roof level)	7/10/06	1	2.940	Asbestos	PCME	EMSL	7/11/06	< 0.00084	No	No		
ASBESTOS-ST7-7/10/06	030621169-0002	Southeast Area (roof level)	7/10/06	1	2.940	Asbestos	PCME	EMSL	7/11/06	< 0.00084	No	No		
ASBESTOS-ST8-7/10/06	030621169-0003	Northwest Area (roof level)	7/10/06	1	2.940	Asbestos	PCME	EMSL	7/11/06	< 0.00084	No	No		
ASBESTOS-ST9-7/10/06	030621169-0004	Northwest Area (roof level)	7/10/06	1	2.940	Asbestos	PCME	EMSL	7/11/06	< 0.00084	No	No		
ASBESTOS-ST10-7/10/06	030621166-0005	North Side Sidewalk Bridge	7/10/06	1	2.940	Asbestos	PCME	EMSL	7/11/06	< 0.00084	No	No		
ASBESTOS-ST11-7/10/06	030621166-0006	90 Trinity Place (roof level)	7/10/06	1	2.940	Asbestos	PCME	EMSL	7/11/06	< 0.00084	No	No		
ASBESTOS-ST12-7/10/06	030621166-0007	110 Greenwich Street (roof level)	7/10/06	1	2.940	Asbestos	PCME	EMSL	7/11/06	< 0.00084	No	No		
ASBESTOS-ST13-7/10/06	030621166-0008	Marriott Hotel, 38th Floor (roof level)	7/10/06	1	2.940	Asbestos	PCME	EMSL	7/11/06	< 0.00084	No	No		
ASBESTOS-ST14-7/10/06	030621166-0009	West Face - South end at corner (scaffolding level)	7/10/06	1	2.940	Asbestos	PCME	EMSL	7/11/06	< 0.00084	No	No		
ASBESTOS-ST15-7/10/06	030621166-0010	South Face - East end at corner (scaffolding level)	7/10/06	1	2.940	Asbestos	PCME	EMSL	7/11/06	< 0.00084	No	No		
ASBESTOS-ST16-7/10/06	030621166-0011	East Face - North end at corner (scaffolding level)	7/10/06	1	2.940	Asbestos	PCME	EMSL	7/11/06	< 0.00084	No	No		
ASBESTOS-ST17-7/10/06	030621166-0012	North Face - West end at corner (scaffolding level)	7/10/06	1	2.940	Asbestos	PCME	EMSL	7/11/06	< 0.00084	No	No		
ASBESTOS-ST1-7/11/06	030621343-0001	Southwest Area (sidewalk bridge level)	7/11/06	1	2.940	Asbestos	PCME	EMSL	7/12/06	< 0.00084	No	No		
ASBESTOS-ST2-7/11/06	030621343-0002	Southeast Area (sidewalk bridge level)	7/11/06	1	2.940	Asbestos	PCME	EMSL	7/12/06	< 0.00084	No	No		
ASBESTOS-ST4-7/11/06	030621343-0003	Northwest Area (street-level)	7/11/06	1	2.940	Asbestos	PCME	EMSL	7/12/06	< 0.00084	No	No		
ASBESTOS-ST5-7/11/06	030621343-0004	Firehouse #10 (roof level)	7/11/06	1	2.940	Asbestos	PCME	EMSL	7/12/06	< 0.00084	No	No		
ASBESTOS-ST6-7/11/06	030621344-0001	Southwest Area (roof level)	7/11/06	1	2.940	Asbestos	PCME	EMSL	7/12/06	< 0.00084	No	No		
ASBESTOS-ST7-7/11/06	030621344-0002	Southeast Area (roof level)	7/11/06	1	2.940	Asbestos	PCME	EMSL	7/12/06	< 0.00084	No	No		
ASBESTOS-ST8-7/11/06	030621344-0003	Northeast Area (roof level)	7/11/06	1	2.940	Asbestos	PCME	EMSL	7/12/06	< 0.00084	No	No		
ASBESTOS-ST9-7/11/06	030621344-0004	Northwest Area (roof level)	7/11/06	1	2.940	Asbestos	PCME	EMSL	7/12/06	< 0.00084	No	No		
ASBESTOS-ST10-7/11/06	030621343-0005	North Side Sidewalk Bridge	7/11/06	1	2.940	Asbestos	PCME	EMSL	7/12/06	< 0.00084	No	No		
ASBESTOS-ST11-7/11/06	030621343-0006	90 Trinity Place (roof level)	7/11/06	1	2.940	Asbestos	PCME	EMSL	7/12/06	< 0.00084	No	No		
ASBESTOS-ST12-7/11/06	030621343-0007	110 Greenwich Street (roof level)	7/11/06	1	2.940	Asbestos	PCME	EMSL	7/12/06	< 0.00084	No	No		
ASBESTOS-ST13-7/11/06	030621343-0008	Marriott Hotel, 38th Floor (roof level)	7/11/06	1	2.940	Asbestos	PCME	EMSL	7/12/06	< 0.00084	No	No		
ASBESTOS-ST14-7/11/06	030621343-0009	West Face - South end at corner (scaffolding level)	7/11/06	1	2.940	Asbestos	PCME	EMSL	7/12/06	< 0.00084	No	No		
ASBESTOS-ST15-7/11/06	030621343-0010	South Face - East end at corner (scaffolding level)	7/11/06	1	2.940	Asbestos	PCME	EMSL	7/12/06	< 0.00084	No	No		
ASBESTOS-ST16-7/11/06	030621343-0011	East Face - North end at corner (scaffolding level)	7/11/06	1	2.940	Asbestos	PCME	EMSL	7/12/06	< 0.00084	No	No		
ASBESTOS-ST17-7/11/06	030621343-0012	North Face - West end at corner (scaffolding level)	7/11/06	1	2.940	Asbestos	PCME	EMSL	7/12/06	< 0.00084	No	No		