

| TRC Field Sample No. | Sample No. | Sampling Location | Collection Start Date | Work Shift | Sample Volume (m ³) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Asbestos PCME Concentration (f/cm3) | Exceeds Target Air Quality Levels | Exceeds EPA Site Specific Trigger Levels | Comments |
|---|----------------|---|-----------------------|------------|---------------------------------|----------|-------------------|------|-------------------------|-------------------------------------|-----------------------------------|--|----------|
| Target Air Quality Levels | | | | | | | | | | 0.0009 | | | |
| EPA Site Specific Trigger Levels | | | | | | | | | | NA | | | |
| ASBESTOS-ST1-7/20/09 | 030918512-0001 | Southwest Area (sidewalk bridge level) | 7/20/09 | 1 | 3.050 | Asbestos | PCME | EMSL | 7/21/09 | < 0.00081 | No | No | |
| ASBESTOS-ST2-7/20/09 | 030918512-0002 | Southeast Area (sidewalk bridge level) | 7/20/09 | 1 | 3.040 | Asbestos | PCME | EMSL | 7/21/09 | < 0.00081 | No | No | |
| ASBESTOS-ST4-7/20/09 | 030918512-0003 | Northwest Area (street-level) | 7/20/09 | 1 | 3.020 | Asbestos | PCME | EMSL | 7/21/09 | < 0.00082 | No | No | |
| ASBESTOS-ST5-7/20/09 | 030918512-0004 | Firehouse #10 (roof level) | 7/20/09 | 1 | 3.000 | Asbestos | PCME | EMSL | 7/21/09 | < 0.00082 | No | No | |
| ASBESTOS-ST10-7/20/09 | 030918512-0005 | North Side Sidewalk Bridge | 7/20/09 | 1 | 3.080 | Asbestos | PCME | EMSL | 7/21/09 | < 0.00080 | No | No | |
| ASBESTOS-ST11-7/20/09 | 030918512-0006 | 90 Trinity Place (roof level) | 7/20/09 | 1 | 3.040 | Asbestos | PCME | EMSL | 7/21/09 | < 0.00081 | No | No | |
| ASBESTOS-ST12-7/20/09 | 030918512-0007 | 110 Greenwich Street (roof level) | 7/20/09 | 1 | 3.010 | Asbestos | PCME | EMSL | 7/21/09 | < 0.00082 | No | No | |
| ASBESTOS-ST13-7/20/09 | 030918512-0008 | Marriott Hotel, 38th Floor (roof level) | 7/20/09 | 1 | 3.070 | Asbestos | PCME | EMSL | 7/21/09 | < 0.00080 | No | No | |
| ASBESTOS-ST1-7/21/09 | 030918661-0001 | Southwest Area (sidewalk bridge level) | 7/21/09 | 1 | 3.120 | Asbestos | PCME | EMSL | 7/22/09 | < 0.00079 | No | No | |
| ASBESTOS-ST2-7/21/09 | 030918661-0002 | Southeast Area (sidewalk bridge level) | 7/21/09 | 1 | 3.130 | Asbestos | PCME | EMSL | 7/22/09 | < 0.00079 | No | No | |
| ASBESTOS-ST4-7/21/09 | 030918661-0003 | Northwest Area (street-level) | 7/21/09 | 1 | 3.040 | Asbestos | PCME | EMSL | 7/22/09 | < 0.00081 | No | No | |
| ASBESTOS-ST5-7/21/09 | 030918661-0004 | Firehouse #10 (roof level) | 7/21/09 | 1 | 3.080 | Asbestos | PCME | EMSL | 7/22/09 | < 0.00080 | No | No | |
| ASBESTOS-ST10-7/21/09 | 030918661-0005 | North Side Sidewalk Bridge | 7/21/09 | 1 | 3.150 | Asbestos | PCME | EMSL | 7/22/09 | < 0.00078 | No | No | |
| ASBESTOS-ST11-7/21/09 | 030918661-0006 | 90 Trinity Place (roof level) | 7/21/09 | 1 | 3.090 | Asbestos | PCME | EMSL | 7/22/09 | < 0.00080 | No | No | |
| ASBESTOS-ST12-7/21/09 | 030918661-0007 | 110 Greenwich Street (roof level) | 7/21/09 | 1 | 3.080 | Asbestos | PCME | EMSL | 7/22/09 | < 0.00080 | No | No | |
| ASBESTOS-ST13-7/21/09 | 030918661-0008 | Marriott Hotel, 38th Floor (roof level) | 7/21/09 | 1 | 3.080 | Asbestos | PCME | EMSL | 7/22/09 | < 0.00080 | No | No | |