

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
Target Air Quality Levels													
EPA Site Specific Trigger Levels													
ASBESTOS-ST1-8/30/06	030628541-0001	Southwest Area (sidewalk bridge level)	8/30/06	1	2.970	Asbestos	PCME	EMSL	8/31/06	< 0.00083	No	No	
ASBESTOS-ST2-8/30/06	030628541-0002	Southeast Area (sidewalk bridge level)	8/30/06	1	2.970	Asbestos	PCME	EMSL	8/31/06	< 0.00083	No	No	
ASBESTOS-ST4-8/30/06	030628541-0003	Northwest Area (street-level)	8/30/06	1	2.970	Asbestos	PCME	EMSL	8/31/06	< 0.00083	No	No	
ASBESTOS-ST5-8/30/06	030628541-0004	Firehouse #10 (roof level)	8/30/06	1	2.970	Asbestos	PCME	EMSL	8/31/06	< 0.00083	No	No	
ASBESTOS-ST6-8/30/06	030628542-0001	Southwest Area (roof level)	8/30/06	1	2.970	Asbestos	PCME	EMSL	8/31/06	< 0.00083	No	No	
ASBESTOS-ST7-8/30/06	030628542-0002	Southeast Area (roof level)	8/30/06	1	2.970	Asbestos	PCME	EMSL	8/31/06	< 0.00083	No	No	
ASBESTOS-ST8-8/30/06	030628542-0003	Northeast Area (roof level)	8/30/06	1	2.970	Asbestos	PCME	EMSL	8/31/06	< 0.00083	No	No	
ASBESTOS-ST9-8/30/06	030628542-0004	Northwest Area (roof level)	8/30/06	1	2.970	Asbestos	PCME	EMSL	8/31/06	< 0.00083	No	No	
ASBESTOS-ST10-8/30/06	030628541-0005	North Side Sidewalk Bridge	8/30/06	1	2.970	Asbestos	PCME	EMSL	8/31/06	< 0.00083	No	No	
ASBESTOS-ST11-8/30/06	030628541-0006	90 Trinity Place (roof level)	8/30/06	1	2.970	Asbestos	PCME	EMSL	8/31/06	< 0.00083	No	No	
ASBESTOS-ST12-8/30/06	030628541-0007	110 Greenwich Street (roof level)	8/30/06	1	2.970	Asbestos	PCME	EMSL	8/31/06	< 0.00083	No	No	
ASBESTOS-ST13-8/30/06	030628541-0008	Marriott Hotel, 38th Floor (roof level)	8/30/06	1	2.970	Asbestos	PCME	EMSL	8/31/06	< 0.00083	No	No	
ASBESTOS-ST14-8/30/06	030628541-0009	West Face - South end at corner (scaffolding level)	8/30/06	1	2.930	Asbestos	PCME	EMSL	8/31/06	< 0.00084	No	No	
ASBESTOS-ST15-8/30/06	030628541-0010	South Face - East end at corner (scaffolding level)	8/30/06	1	2.970	Asbestos	PCME	EMSL	8/31/06	< 0.00083	No	No	
ASBESTOS-ST16-8/30/06	030628541-0011	East Face - North end at corner (scaffolding level)	8/30/06	1	2.970	Asbestos	PCME	EMSL	8/31/06	< 0.00083	No	No	
ASBESTOS-ST17-8/30/06	030628541-0012	North Face - West end at corner (scaffolding level)	8/30/06	1	2.880	Asbestos	PCME	EMSL	8/31/06	< 0.00086	No	No	
ASBESTOS-ST1-8/31/06	030628686-0001	Southwest Area (sidewalk bridge level)	8/31/06	1	3.020	Asbestos	PCME	EMSL	9/1/06	< 0.00082	No	No	
ASBESTOS-ST2-8/31/06	030628686-0002	Southeast Area (sidewalk bridge level)	8/31/06	1	3.020	Asbestos	PCME	EMSL	9/1/06	< 0.00082	No	No	
ASBESTOS-ST4-8/31/06	030628686-0003	Northwest Area (street-level)	8/31/06	1	3.020	Asbestos	PCME	EMSL	9/1/06	< 0.00082	No	No	
ASBESTOS-ST5-8/31/06	030628686-0004	Firehouse #10 (roof level)	8/31/06	1	3.020	Asbestos	PCME	EMSL	9/1/06	< 0.00082	No	No	
ASBESTOS-ST6-8/31/06	030628687-0001	Southwest Area (roof level)	8/31/06	1	3.020	Asbestos	PCME	EMSL	9/1/06	< 0.00082	No	No	
ASBESTOS-ST7-8/31/06	030628687-0002	Southeast Area (roof level)	8/31/06	1	3.020	Asbestos	PCME	EMSL	9/1/06	< 0.00082	No	No	
ASBESTOS-ST8-8/31/06	030628687-0003	Northeast Area (roof level)	8/31/06	1	3.020	Asbestos	PCME	EMSL	9/1/06	< 0.00082	No	No	
ASBESTOS-ST9-8/31/06	030628687-0004	Northwest Area (roof level)	8/31/06	1	3.020	Asbestos	PCME	EMSL	9/1/06	< 0.00082	No	No	
ASBESTOS-ST10-8/31/06	030628686-0005	North Side Sidewalk Bridge	8/31/06	1	3.020	Asbestos	PCME	EMSL	9/1/06	< 0.00082	No	No	
ASBESTOS-ST11-8/31/06	030628686-0006	90 Trinity Place (roof level)	8/31/06	1	3.020	Asbestos	PCME	EMSL	9/1/06	< 0.00082	No	No	
ASBESTOS-ST12-8/31/06	030628686-0007	110 Greenwich Street (roof level)	8/31/06	1	3.020	Asbestos	PCME	EMSL	9/1/06	< 0.00082	No	No	
ASBESTOS-ST13-8/31/06	030628686-0008	Marriott Hotel, 38th Floor (roof level)	8/31/06	1	3.020	Asbestos	PCME	EMSL	9/1/06	< 0.00082	No	No	
ASBESTOS-ST14-8/31/06	030628686-0009	West Face - South end at corner (scaffolding level)	8/31/06	1	3.020	Asbestos	PCME	EMSL	9/1/06	< 0.00082	No	No	
ASBESTOS-ST15-8/31/06	030628686-0010	South Face - East end at corner (scaffolding level)	8/31/06	1	2.900	Asbestos	PCME	EMSL	9/1/06	< 0.00085	No	No	
ASBESTOS-ST16-8/31/06	030628686-0011	East Face - North end at corner (scaffolding level)	8/31/06	1	2.960	Asbestos	PCME	EMSL	9/1/06	< 0.00083	No	No	
ASBESTOS-ST17-8/31/06	030628686-0012	North Face - West end at corner (scaffolding level)	8/31/06	1	3.020	Asbestos	PCME	EMSL	9/1/06	< 0.00082	No	No	