

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										0.0009			
										NA			
ASBESTOS-ST1-9/10/08	030831898-0001	Southwest Area (sidewalk bridge level)	9/10/08	1	6.180	Asbestos	PCME	EMSL	9/12/08	< 0.00080	No	No	
ASBESTOS-ST2-9/10/08	030831898-0002	Southeast Area (sidewalk bridge level)	9/10/08	1	6.040	Asbestos	PCME	EMSL	9/12/08	< 0.00082	No	No	
ASBESTOS-ST4-9/10/08	030831898-0003	Northwest Area (street-level)	9/10/08	1	6.100	Asbestos	PCME	EMSL	9/12/08	< 0.00081	No	No	
ASBESTOS-ST5-9/10/08	030831898-0004	Firehouse #10 (roof level)	9/10/08	1	6.140	Asbestos	PCME	EMSL	9/12/08	< 0.00080	No	No	
ASBESTOS-ST10-9/10/08	030831898-0005	North Side Sidewalk Bridge	9/10/08	1	6.190	Asbestos	PCME	EMSL	9/12/08	< 0.00080	No	No	
ASBESTOS-ST11-9/10/08	030831898-0006	90 Trinity Place (roof level)	9/10/08	1	6.250	Asbestos	PCME	EMSL	9/12/08	< 0.00079	No	No	
ASBESTOS-ST12-9/10/08	030831898-0007	110 Greenwich Street (roof level)	9/10/08	1	6.100	Asbestos	PCME	EMSL	9/12/08	< 0.00081	No	No	
ASBESTOS-ST13-9/10/08	030831898-0008	Marriott Hotel, 38th Floor (roof level)	9/10/08	1	5.940	Asbestos	PCME	EMSL	9/12/08	< 0.00083	No	No	
ASBESTOS-ST14-9/10/08	030831898-0009	West Face - South end at corner (scaffolding level)	9/10/08	1	6.010	Asbestos	PCME	EMSL	9/12/08	< 0.00082	No	No	
ASBESTOS-ST15-9/10/08	030831898-0010	South Face - East end at corner (scaffolding level)	9/10/08	1	6.040	Asbestos	PCME	EMSL	9/12/08	< 0.00082	No	No	
ASBESTOS-ST16-9/10/08	030831898-0011	East Face - North end at corner (scaffolding level)	9/10/08	1	6.260	Asbestos	PCME	EMSL	9/12/08	< 0.00079	No	No	
ASBESTOS-ST17-9/10/08	030831898-0012	North Face - West end at corner (scaffolding level)	9/10/08	1	6.190	Asbestos	PCME	EMSL	9/12/08	< 0.00080	No	No	
ASBESTOS-ST1-9/12/08	030832040-0001	Southwest Area (sidewalk bridge level)	9/12/08	1	3.040	Asbestos	PCME	EMSL	9/13/08	< 0.00081	No	No	
ASBESTOS-ST2-9/12/08	030832040-0002	Southeast Area (sidewalk bridge level)	9/12/08	1	3.080	Asbestos	PCME	EMSL	9/13/08	< 0.00080	No	No	
ASBESTOS-ST4-9/12/08	030832040-0003	Northwest Area (street-level)	9/12/08	1	2.980	Asbestos	PCME	EMSL	9/13/08	< 0.00083	No	No	
ASBESTOS-ST5-9/12/08	030832040-0004	Firehouse #10 (roof level)	9/12/08	1	2.990	Asbestos	PCME	EMSL	9/13/08	< 0.00083	No	No	
ASBESTOS-ST10-9/12/08	030832040-0005	North Side Sidewalk Bridge	9/12/08	1	3.040	Asbestos	PCME	EMSL	9/13/08	< 0.00081	No	No	
ASBESTOS-ST11-9/12/08	030832040-0006	90 Trinity Place (roof level)	9/12/08	1	3.040	Asbestos	PCME	EMSL	9/13/08	< 0.00081	No	No	
ASBESTOS-ST12-9/12/08	030832040-0007	110 Greenwich Street (roof level)	9/12/08	1	3.090	Asbestos	PCME	EMSL	9/13/08	< 0.00080	No	No	
ASBESTOS-ST13-9/12/08	030832040-0008	Marriott Hotel, 38th Floor (roof level)	9/12/08	1	3.070	Asbestos	PCME	EMSL	9/13/08	< 0.00080	No	No	
ASBESTOS-ST14-9/12/08	030832040-0009	West Face - South end at corner (scaffolding level)	9/12/08	1	2.860	Asbestos	PCME	EMSL	9/13/08	< 0.00086	No	No	
ASBESTOS-ST15-9/12/08	030832040-0010	South Face - East end at corner (scaffolding level)	9/12/08	1	2.980	Asbestos	PCME	EMSL	9/13/08	< 0.00083	No	No	
ASBESTOS-ST16-9/12/08	030832040-0011	East Face - North end at corner (scaffolding level)	9/12/08	1	2.890	Asbestos	PCME	EMSL	9/13/08	< 0.00085	No	No	
ASBESTOS-ST17-9/12/08	030832040-0012	North Face - West end at corner (scaffolding level)	9/12/08	1	2.910	Asbestos	PCME	EMSL	9/13/08	< 0.00085	No	No	

Note:
1. Due to site accessibility restrictions, the asbestos samples at all stations on September 10, 2008 were not retrieved until September 12, 2008 and therefore represent 48-hour composite samples (September 10 through September 11).