

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
3 * Target Air Quality Levels										0.0027	Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	
EPA Site Specific Trigger Levels										NA			
ASBESTOS-ST1-9/14/05	030527463-0001	Southwest Corner (street-level)	9/14/2005	1	2.880	Asbestos	PCME	EMSL	9/15/2005	< 0.00086	No	No	
ASBESTOS-ST2-9/14/05	030527463-0002	Southeast Corner (street-level)	9/14/2005	1	2.880	Asbestos	PCME	EMSL	9/15/2005	< 0.00086	No	No	
ASBESTOS-ST3-9/14/05	030527463-0003	Northeast Area (street-level)	9/14/2005	1	2.880	Asbestos	PCME	EMSL	9/15/2005	< 0.00086	No	No	
ASBESTOS-ST4-9/14/05	030527463-0004	Northwest Side (street-level)	9/14/2005	1	2.880	Asbestos	PCME	EMSL	9/15/2005	< 0.00086	No	No	
ASBESTOS-ST5-9/14/05	030527463-0005	Firehouse #10 Roof (roof-top)	9/14/2005	1	2.880	Asbestos	PCME	EMSL	9/15/2005	< 0.00086	No	No	
ASBESTOS-ST6-9/14/05	030527463-0006	Southwest Corner (roof-top)	9/14/2005	1	2.880	Asbestos	PCME	EMSL	9/15/2005	< 0.00086	No	No	
ASBESTOS-ST7-9/14/05	030527463-0007	Southeast Corner (roof-top)	9/14/2005	1	2.880	Asbestos	PCME	EMSL	9/15/2005	< 0.00086	No	No	
ASBESTOS-ST8-9/14/05	030527463-0008	Northeast Side (roof-top)	9/14/2005	1	8.060	Asbestos	PCME	EMSL	9/15/2005	< 0.00031	No	No	
ASBESTOS-ST9-9/14/05	030527463-0009	Northwest Corner (roof-top)	9/14/2005	1	2.880	Asbestos	PCME	EMSL	9/15/2005	< 0.00086	No	No	
ASBESTOS-ST1-9/15/05	030527557-0001	Southwest Corner (street-level)	9/15/2005	1	2.880	Asbestos	PCME	EMSL	9/16/2005	< 0.00079	No	No	
ASBESTOS-ST2-9/15/05	030527557-0002	Southeast Corner (street-level)	9/15/2005	1	2.880	Asbestos	PCME	EMSL	9/16/2005	< 0.00079	No	No	
ASBESTOS-ST3-9/15/05	030527557-0003	Northeast Area (street-level)	9/15/2005	1	2.880	Asbestos	PCME	EMSL	9/16/2005	< 0.00079	No	No	
ASBESTOS-ST4-9/15/05	030527557-0004	Northwest Side (street-level)	9/15/2005	1	2.880	Asbestos	PCME	EMSL	9/16/2005	< 0.00079	No	No	
ASBESTOS-ST5-9/15/05	030527557-0005	Firehouse #10 Roof (roof-top)	9/15/2005	1	2.880	Asbestos	PCME	EMSL	9/16/2005	< 0.00079	No	No	
ASBESTOS-ST6-9/15/05	030527557-0006	Southwest Corner (roof-top)	9/15/2005	1	2.880	Asbestos	PCME	EMSL	9/16/2005	< 0.00079	No	No	
ASBESTOS-ST7-9/15/05	030527557-0007	Southeast Corner (roof-top)	9/15/2005	1	2.880	Asbestos	PCME	EMSL	9/16/2005	< 0.00079	No	No	
ASBESTOS-ST8-9/15/05	030527557-0008	Northeast Side (roof-top)	9/15/2005	1	2.880	Asbestos	PCME	EMSL	9/16/2005	< 0.00079	No	No	
ASBESTOS-ST9-9/15/05	030527557-0009	Northwest Corner (roof-top)	9/15/2005	1	2.880	Asbestos	PCME	EMSL	9/16/2005	< 0.00079	No	No	