

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										0.0009			
EPA Site Specific Trigger Levels										NA			
ASBESTOS-ST1-10/12/09	030926118-0001	Southwest Area (sidewalk bridge level)	10/12/09	1	3.120	Asbestos	PCME	EMSL	10/13/09	< 0.00079	No	No	
ASBESTOS-ST2-10/12/09	030926118-0002	Southeast Area (sidewalk bridge level)	10/12/09	1	3.200	Asbestos	PCME	EMSL	10/13/09	< 0.00077	No	No	
ASBESTOS-ST4-10/12/09	030926118-0003	Northwest Area (street-level)	10/12/09	1	3.210	Asbestos	PCME	EMSL	10/13/09	< 0.00077	No	No	
ASBESTOS-ST5-10/12/09	030926118-0004	Firehouse #10 (roof level)	10/12/09	1	3.070	Asbestos	PCME	EMSL	10/13/09	< 0.00080	No	No	
ASBESTOS-ST10-10/12/09	030926118-0005	North Side Sidewalk Bridge	10/12/09	1	3.070	Asbestos	PCME	EMSL	10/13/09	< 0.00080	No	No	
ASBESTOS-ST11-10/12/09	030926118-0006	90 Trinity Place (roof level)	10/12/09	1	2.890	Asbestos	PCME	EMSL	10/13/09	< 0.00085	No	No	
ASBESTOS-ST12-10/12/09	030926118-0007	110 Greenwich Street (roof level)	10/12/09	1	3.140	Asbestos	PCME	EMSL	10/13/09	< 0.00079	No	No	
ASBESTOS-ST13-10/12/09	030926118-0008	Marriott Hotel, 38th Floor (roof level)	10/12/09	1	3.150	Asbestos	PCME	EMSL	10/13/09	< 0.00078	No	No	
ASBESTOS-ST1-10/13/09	030926234-0001	Southwest Area (sidewalk bridge level)	10/13/09	1	2.940	Asbestos	PCME	EMSL	10/14/09	< 0.00077	No	No	
ASBESTOS-ST2-10/13/09	030926234-0002	Southeast Area (sidewalk bridge level)	10/13/09	1	2.900	Asbestos	PCME	EMSL	10/14/09	< 0.00079	No	No	
ASBESTOS-ST4-10/13/09	030926234-0003	Northwest Area (street-level)	10/13/09	1	2.980	Asbestos	PCME	EMSL	10/14/09	< 0.00076	No	No	
ASBESTOS-ST5-10/13/09	030926234-0004	Firehouse #10 (roof level)	10/13/09	1	2.930	Asbestos	PCME	EMSL	10/14/09	< 0.00078	No	No	
ASBESTOS-ST10-10/13/09	030926234-0005	North Side Sidewalk Bridge	10/13/09	1	2.940	Asbestos	PCME	EMSL	10/14/09	< 0.00077	No	No	
ASBESTOS-ST100-10/13/09	030926234-0009	Station 10 Field Duplicate	10/13/09	1	2.930	Asbestos	PCME	EMSL	10/14/09	< 0.00078	No	No	
ASBESTOS-ST11-10/13/09	030926234-0006	90 Trinity Place (roof level)	10/13/09	1	3.070	Asbestos	PCME	EMSL	10/14/09	< 0.00080	No	No	
ASBESTOS-ST12-10/13/09	030926234-0007	110 Greenwich Street (roof level)	10/13/09	1	3.110	Asbestos	PCME	EMSL	10/14/09	< 0.00079	No	No	
ASBESTOS-ST13-10/13/09	030926234-0008	Marriott Hotel, 38th Floor (roof level)	10/13/09	1	3.030	Asbestos	PCME	EMSL	10/14/09	< 0.00081	No	No	

Note:

- Asbestos sample results are not available on October 11, 2009 since no sampling was conducted on this day due to the lack of work activities. This is in accordance with Amendment #9 to the September 2005 Ambient Air Monitoring Program Plan.