

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
										Target Air Quality Levels			
										EPA Site Specific Trigger Levels			
ASBESTOS-ST1-12/26/07	030739876-0001	Southwest Area (sidewalk bridge level)	12/26/07	1	3.010	Asbestos	PCME	EMSL	12/27/07	< 0.00089	No	No	
ASBESTOS-ST2-12/26/07	030739876-0002	Southeast Area (sidewalk bridge level)	12/26/07	1	3.010	Asbestos	PCME	EMSL	12/27/07	< 0.00089	No	No	
ASBESTOS-ST4-12/26/07	030739876-0003	Northwest Area (street-level)	12/26/07	1	3.040	Asbestos	PCME	EMSL	12/27/07	< 0.00089	No	No	
ASBESTOS-ST5-12/26/07	030739876-0004	Firehouse #10 (roof level)	12/26/07	1	3.060	Asbestos	SEM	EMSL	12/27/07	< 0.00090	No	No	
ASBESTOS-ST10-12/26/07	030739876-0005	North Side Sidewalk Bridge	12/26/07	1	3.010	Asbestos	PCME	EMSL	12/27/07	< 0.00089	No	No	
ASBESTOS-ST11-12/26/07	030739876-0006	90 Trinity Place (roof level)	12/26/07	1	3.010	Asbestos	PCME	EMSL	12/27/07	< 0.00089	No	No	
ASBESTOS-ST12-12/26/07	030739876-0007	110 Greenwich Street (roof level)	12/26/07	1	3.010	Asbestos	PCME	EMSL	12/27/07	< 0.00089	No	No	
ASBESTOS-ST13-12/26/07	030739876-0008	Marriott Hotel, 38th Floor (roof level)	12/26/07	1	3.010	Asbestos	PCME	EMSL	12/27/07	< 0.00089	No	No	
ASBESTOS-ST14-12/26/07	030739876-0009	West Face - South end at corner (scaffolding level)	12/26/07	1	3.010	Asbestos	PCME	EMSL	12/27/07	< 0.00089	No	No	
ASBESTOS-ST15-12/26/07	030739876-0010	South Face - East end at corner (scaffolding level)	12/26/07	1	3.130	Asbestos	SEM	EMSL	12/27/07	< 0.00090	No	No	
ASBESTOS-ST16-12/26/07	030739876-0011	East Face - North end at corner (scaffolding level)	12/26/07	1	3.020	Asbestos	PCME	EMSL	12/27/07	< 0.00089	No	No	
ASBESTOS-ST17-12/26/07	030739876-0012	North Face - West end at corner (scaffolding level)	12/26/07	1	3.020	Asbestos	PCME	EMSL	12/27/07	< 0.00082	No	No	
ASBESTOS-ST1-12/27/07	030739956-0001	Southwest Area (sidewalk bridge level)	12/27/07	1	3.000	Asbestos	PCME	EMSL	12/28/07	< 0.00082	No	No	
ASBESTOS-ST2-12/27/07	030739956-0002	Southeast Area (sidewalk bridge level)	12/27/07	1	2.960	Asbestos	PCME	EMSL	12/28/07	< 0.00083	No	No	
ASBESTOS-ST4-12/27/07	030739956-0003	Northwest Area (street-level)	12/27/07	1	3.030	Asbestos	PCME	EMSL	12/28/07	< 0.00081	No	No	
ASBESTOS-ST5-12/27/07	030739956-0004	Firehouse #10 (roof level)	12/27/07	1	3.230	Asbestos	PCME	EMSL	12/28/07	< 0.00083	No	No	
ASBESTOS-ST10-12/27/07	030739956-0005	North Side Sidewalk Bridge	12/27/07	1	3.090	Asbestos	PCME	EMSL	12/28/07	< 0.00087	No	No	
ASBESTOS-ST100-12/27/07	030739956-0013	Station 10 Field Duplicate	12/27/07	1	2.950	Asbestos	PCME	EMSL	12/28/07	< 0.00084	No	No	
ASBESTOS-ST11-12/27/07	030739956-0006	90 Trinity Place (roof level)	12/27/07	1	3.040	Asbestos	PCME	EMSL	12/28/07	< 0.00081	No	No	
ASBESTOS-ST12-12/27/07	030739956-0007	110 Greenwich Street (roof level)	12/27/07	1	3.010	Asbestos	PCME	EMSL	12/28/07	< 0.00082	No	No	
ASBESTOS-ST13-12/27/07	030739956-0008	Marriott Hotel, 38th Floor (roof level)	12/27/07	1	2.870	Asbestos	PCME	EMSL	12/28/07	< 0.00086	No	No	
ASBESTOS-ST14-12/27/07	030739956-0009	West Face - South end at corner (scaffolding level)	12/27/07	1	3.000	Asbestos	PCME	EMSL	12/28/07	< 0.00082	No	No	
ASBESTOS-ST15-12/27/07	030739956-0010	South Face - East end at corner (scaffolding level)	12/27/07	1	3.040	Asbestos	PCME	EMSL	12/28/07	< 0.00089	No	No	
ASBESTOS-ST16-12/27/07	030739956-0011	East Face - North end at corner (scaffolding level)	12/27/07	1	3.060	Asbestos	PCME	EMSL	12/28/07	< 0.00088	No	No	
ASBESTOS-ST17-12/27/07	030739956-0012	North Face - West end at corner (scaffolding level)	12/27/07	1	3.010	Asbestos	PCME	EMSL	12/28/07	< 0.00089	No	No	
ASBESTOS-ST1-12/28/07	030740071-0001	Southwest Area (sidewalk bridge level)	12/28/07	1	3.060	Asbestos	PCME	EMSL	12/29/07	< 0.00081	No	No	
ASBESTOS-ST2-12/28/07	030740071-0002	Southeast Area (sidewalk bridge level)	12/28/07	1	3.070	Asbestos	PCME	EMSL	12/29/07	< 0.00080	No	No	
ASBESTOS-ST4-12/28/07	030740071-0003	Northwest Area (street-level)	12/28/07	1	3.010	Asbestos	PCME	EMSL	12/29/07	< 0.00082	No	No	
ASBESTOS-ST5-12/28/07	030740071-0004	Firehouse #10 (roof level)	12/28/07	1	3.180	Asbestos	PCME	EMSL	12/29/07	< 0.00078	No	No	
ASBESTOS-ST10-12/28/07	030740071-0005	North Side Sidewalk Bridge	12/28/07	1	3.090	Asbestos	PCME	EMSL	12/29/07	< 0.00080	No	No	
ASBESTOS-ST11-12/28/07	030740071-0006	90 Trinity Place (roof level)	12/28/07	1	3.000	Asbestos	PCME	EMSL	12/29/07	< 0.00082	No	No	
ASBESTOS-ST12-12/28/07	030740071-0007	110 Greenwich Street (roof level)	12/28/07	1	3.010	Asbestos	PCME	EMSL	12/29/07	< 0.00082	No	No	
ASBESTOS-ST13-12/28/07	030740071-0008	Marriott Hotel, 38th Floor (roof level)	12/28/07	1	3.040	Asbestos	PCME	EMSL	12/29/07	< 0.00081	No	No	
ASBESTOS-ST14-12/28/07	030740071-0009	West Face - South end at corner (scaffolding level)	12/28/07	1	3.040	Asbestos	PCME	EMSL	12/29/07	< 0.00081	No	No	
ASBESTOS-ST15-12/28/07	030740071-0010	South Face - East end at corner (scaffolding level)	12/28/07	1	3.050	Asbestos	PCME	EMSL	12/29/07	< 0.00081	No	No	
ASBESTOS-ST16-12/28/07	030740071-0011	East Face - North end at corner (scaffolding level)	12/28/07	1	2.950	Asbestos	PCME	EMSL	12/29/07	< 0.00084	No	No	
ASBESTOS-ST17-12/28/07	030740071-0012	North Face - West end at corner (scaffolding level)	12/28/07	1	2.990	Asbestos	PCME	EMSL	12/29/07	< 0.00083	No	No	