

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels							150			
EPA Site Specific Trigger Levels							150			
PM10-ST1-1/4/2008	Southwest Area (sidewalk bridge level)	1/4/08	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM10-ST2-1/4/2008	Southeast Area (sidewalk bridge level)	1/4/08	1440	Particulate	Direct Read	Met One E-BAM	36	No	No	
PM10-ST4-1/4/2008	Northwest Area (street-level)	1/4/08	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST5-1/4/2008	Firehouse #10 (roof level)	1/4/08	1440	Particulate	Direct Read	Met One E-BAM	31	No	No	
PM10-ST10-1/4/2008	North Side Sidewalk Bridge	1/4/08	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM10-ST100-1/4/2008	Station 10 Field Duplicate	1/4/08	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM10-ST11-1/4/2008	90 Trinity Place (roof level)	1/4/08	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM10-ST12-1/4/2008	110 Greenwich Street (roof level)	1/4/08	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST13-1/4/2008	Marriott Hotel, 38th Floor (roof level)	1/4/08	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST14-1/4/2008	West Face - South end at corner (scaffolding level)	1/4/08	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST15-1/4/2008	South Face - East end at corner (scaffolding level)	1/4/08	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST16-1/4/2008	East Face - North end at corner (scaffolding level)	1/4/08	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST17-1/4/2008	North Face - West end at corner (scaffolding level)	1/4/08	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST1-1/5/2008	Southwest Area (sidewalk bridge level)	1/5/08	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM10-ST2-1/5/2008	Southeast Area (sidewalk bridge level)	1/5/08	1440	Particulate	Direct Read	Met One E-BAM	44	No	No	
PM10-ST4-1/5/2008	Northwest Area (street-level)	1/5/08	1440	Particulate	Direct Read	Met One E-BAM	34	No	No	
PM10-ST5-1/5/2008	Firehouse #10 (roof level)	1/5/08	1440	Particulate	Direct Read	Met One E-BAM	35	No	No	
PM10-ST10-1/5/2008	North Side Sidewalk Bridge	1/5/08	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM10-ST100-1/5/2008	Station 10 Field Duplicate	1/5/08	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST11-1/5/2008	90 Trinity Place (roof level)	1/5/08	1440	Particulate	Direct Read	Met One E-BAM	30	No	No	
PM10-ST12-1/5/2008	110 Greenwich Street (roof level)	1/5/08	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST13-1/5/2008	Marriott Hotel, 38th Floor (roof level)	1/5/08	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM10-ST14-1/5/2008	West Face - South end at corner (scaffolding level)	1/5/08	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM10-ST15-1/5/2008	South Face - East end at corner (scaffolding level)	1/5/08	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST16-1/5/2008	East Face - North end at corner (scaffolding level)	1/5/08	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST17-1/5/2008	North Face - West end at corner (scaffolding level)	1/5/08	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST1-1/6/2008	Southwest Area (sidewalk bridge level)	1/6/08	1440	Particulate	Direct Read	Met One E-BAM	36	No	No	
PM10-ST2-1/6/2008	Southeast Area (sidewalk bridge level)	1/6/08	1440	Particulate	Direct Read	Met One E-BAM	56	No	No	
PM10-ST4-1/6/2008	Northwest Area (street-level)	1/6/08	1440	Particulate	Direct Read	Met One E-BAM	41	No	No	
PM10-ST5-1/6/2008	Firehouse #10 (roof level)	1/6/08	1440	Particulate	Direct Read	Met One E-BAM	43	No	No	
PM10-ST10-1/6/2008	North Side Sidewalk Bridge	1/6/08	1440	Particulate	Direct Read	Met One E-BAM	35	No	No	
PM10-ST100-1/6/2008	Station 10 Field Duplicate	1/6/08	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST11-1/6/2008	90 Trinity Place (roof level)	1/6/08	1440	Particulate	Direct Read	Met One E-BAM	38	No	No	
PM10-ST12-1/6/2008	110 Greenwich Street (roof level)	1/6/08	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM10-ST13-1/6/2008	Marriott Hotel, 38th Floor (roof level)	1/6/08	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST15-1/6/2008	South Face - East end at corner (scaffolding level)	1/6/08	1440	Particulate	Direct Read	Met One E-BAM	35	No	No	
PM10-ST16-1/6/2008	East Face - North end at corner (scaffolding level)	1/6/08	1440	Particulate	Direct Read	Met One E-BAM	32	No	No	
PM10-ST17-1/6/2008	North Face - West end at corner (scaffolding level)	1/6/08	1440	Particulate	Direct Read	Met One E-BAM	35	No	No	

Note:

1. The PM 10 reading at Station 14 (West Face - South end at corner [scaffolding level]) on January 6, 2008 was not available on account of instrument malfunction.