

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
							150			
							150			
PM10-ST1-1/24/2007	Southwest Area (sidewalk bridge level)	1/24/07	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST2-1/24/2007	Southeast Area (sidewalk bridge level)	1/24/07	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST4-1/24/2007	Northwest Area (street-level)	1/24/07	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST5-1/24/2007	Firehouse #10 (roof level)	1/24/07	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST10-1/24/2007	North Side Sidewalk Bridge	1/24/07	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST100-1/24/2007	Station 10 Field Duplicate	1/24/07	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST11-1/24/2007	90 Trinity Place (roof level)	1/24/07	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST12-1/24/2007	110 Greenwich Street (roof level)	1/24/07	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST13-1/24/2007	Marriott Hotel, 38th Floor (roof level)	1/24/07	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST14-1/24/2007	West Face - South end at corner (scaffolding level)	1/24/07	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST15-1/24/2007	South Face - East end at corner (scaffolding level)	1/24/07	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST16-1/24/2007	East Face - North end at corner (scaffolding level)	1/24/07	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST1-1/25/2007	Southwest Area (sidewalk bridge level)	1/25/07	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST2-1/25/2007	Southeast Area (sidewalk bridge level)	1/25/07	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM10-ST4-1/25/2007	Northwest Area (street-level)	1/25/07	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST5-1/25/2007	Firehouse #10 (roof level)	1/25/07	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST10-1/25/2007	North Side Sidewalk Bridge	1/25/07	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST100-1/25/2007	Station 10 Field Duplicate	1/25/07	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST11-1/25/2007	90 Trinity Place (roof level)	1/25/07	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST12-1/25/2007	110 Greenwich Street (roof level)	1/25/07	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST13-1/25/2007	Marriott Hotel, 38th Floor (roof level)	1/25/07	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST14-1/25/2007	West Face - South end at corner (scaffolding level)	1/25/07	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST15-1/25/2007	South Face - East end at corner (scaffolding level)	1/25/07	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST16-1/25/2007	East Face - North end at corner (scaffolding level)	1/25/07	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	

Note:

1. The PM 10 readings at Station 17 (North Face - West end at corner [scaffolding level]) on January 24 and 25, 2007 were not available on account of instrument malfunction.