

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels							150			
EPA Site Specific Trigger Levels							150			
PM10-ST1-2/12/2010	Southwest Area (sidewalk bridge level)	2/12/10	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST2-2/12/2010	Southeast Area (sidewalk bridge level)	2/12/10	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST4-2/12/2010	Northwest Area (street-level)	2/12/10	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST5-2/12/2010	Firehouse #10 (roof level)	2/12/10	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST11-2/12/2010	90 Trinity Place (roof level)	2/12/10	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST12-2/12/2010	110 Greenwich Street (roof level)	2/12/10	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST13-2/12/2010	Marriott Hotel, 38th Floor (roof level)	2/12/10	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST20-2/12/2010	Northeast Area, Sidewalk Bridge	2/12/10	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST200-2/12/2010	Station 20 Field Duplicate	2/12/10	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST1-2/13/2010	Southwest Area (sidewalk bridge level)	2/13/10	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST2-2/13/2010	Southeast Area (sidewalk bridge level)	2/13/10	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST4-2/13/2010	Northwest Area (street-level)	2/13/10	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST5-2/13/2010	Firehouse #10 (roof level)	2/13/10	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST11-2/13/2010	90 Trinity Place (roof level)	2/13/10	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM10-ST12-2/13/2010	110 Greenwich Street (roof level)	2/13/10	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST13-2/13/2010	Marriott Hotel, 38th Floor (roof level)	2/13/10	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM10-ST20-2/13/2010	Northeast Area, Sidewalk Bridge	2/13/10	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST200-2/13/2010	Station 20 Field Duplicate	2/13/10	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST1-2/14/2010	Southwest Area (sidewalk bridge level)	2/14/10	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM10-ST2-2/14/2010	Southeast Area (sidewalk bridge level)	2/14/10	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST4-2/14/2010	Northwest Area (street-level)	2/14/10	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST5-2/14/2010	Firehouse #10 (roof level)	2/14/10	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST11-2/14/2010	90 Trinity Place (roof level)	2/14/10	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST12-2/14/2010	110 Greenwich Street (roof level)	2/14/10	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM10-ST13-2/14/2010	Marriott Hotel, 38th Floor (roof level)	2/14/10	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM10-ST20-2/14/2010	Northeast Area, Sidewalk Bridge	2/14/10	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST200-2/14/2010	Station 20 Field Duplicate	2/14/10	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	