

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels							150			
EPA Site Specific Trigger Levels							150			
PM10-ST1-3/12/2010	Southwest Area (sidewalk bridge level)	3/12/10	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST2-3/12/2010	Southeast Area (sidewalk bridge level)	3/12/10	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM10-ST4-3/12/2010	Northwest Area (street-level)	3/12/10	1440	Particulate	Direct Read	Met One E-BAM	41	No	No	
PM10-ST5-3/12/2010	Firehouse #10 (roof level)	3/12/10	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM10-ST12-3/12/2010	110 Greenwich Street (roof level)	3/12/10	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM10-ST13-3/12/2010	Marriott Hotel, 38th Floor (roof level)	3/12/10	1440	Particulate	Direct Read	Met One E-BAM	30	No	No	
PM10-ST20-3/12/2010	Northeast Area, Sidewalk Bridge	3/12/10	1440	Particulate	Direct Read	Met One E-BAM	35	No	No	
PM10-ST200-3/12/2010	Station 20 Field Duplicate	3/12/10	1440	Particulate	Direct Read	Met One E-BAM	41	No	No	

Note:

1. The PM10 reading from Station 11 (110 Greenwich St [roof level]) on March 12, 2010 was not available on account of instrument malfunction.
2. The PM10 readings are not available for March 13 and 14, 2010 since no sampling was conducted on these days due to the lack of work activities. This is in accordance with Amendment #9 to the September 2005 Ambient Air Monitoring Program Plan.