

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
<b>Target Air Quality Levels</b>							<b>150</b>			
<b>EPA Site Specific Trigger Levels</b>							<b>150</b>			
PM10-ST1-3/22/2006	Southwest Area (sidewalk bridge level)	3/22/06	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST2-3/22/2006	Southeast Area (sidewalk bridge level)	3/22/06	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM10-ST5-3/22/2006	Firehouse #10 (roof level)	3/22/06	1440	Particulate	Direct Read	Met One E-BAM	40	No	No	
PM10-ST10-3/22/2006	North Side Sidewalk Bridge	3/22/06	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST100-3/22/2006	Station 10 Field Duplicate	3/22/06	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST11-3/22/2006	90 Trinity Place (roof level)	3/22/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST12-3/22/2006	110 Greenwich Street (roof level)	3/22/06	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST13-3/22/2006	Marriott Hotel, 38th Floor (roof level)	3/22/06	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST14-3/22/2006	West Face - South end at corner (scaffolding level)	3/22/06	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST15-3/22/2006	South Face - East end at corner (scaffolding level)	3/22/06	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST16-3/22/2006	East Face - North end at corner (scaffolding level)	3/22/06	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM10-ST17-3/22/2006	North Face - West end at corner (scaffolding level)	3/22/06	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM10-ST1-3/23/2006	Southwest Area (sidewalk bridge level)	3/23/06	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST2-3/23/2006	Southeast Area (sidewalk bridge level)	3/23/06	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST4-3/23/2006	Northwest Area (street-level)	3/23/06	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST5-3/23/2006	Firehouse #10 (roof level)	3/23/06	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST10-3/23/2006	North Side Sidewalk Bridge	3/23/06	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST100-3/23/2006	Station 10 Field Duplicate	3/23/06	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST11-3/23/2006	90 Trinity Place (roof level)	3/23/06	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST12-3/23/2006	110 Greenwich Street (roof level)	3/23/06	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM10-ST13-3/23/2006	Marriott Hotel, 38th Floor (roof level)	3/23/06	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM10-ST14-3/23/2006	West Face - South end at corner (scaffolding level)	3/23/06	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM10-ST15-3/23/2006	South Face - East end at corner (scaffolding level)	3/23/06	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST16-3/23/2006	East Face - North end at corner (scaffolding level)	3/23/06	1440	Particulate	Direct Read	Met One E-BAM	4	No	No	
PM10-ST17-3/23/2006	North Face - West end at corner (scaffolding level)	3/23/06	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	

Note:

1. The PM 10 reading at Station 4 (Northwest Area [street level]) on March 22, 2006 was not available on account of instrument malfunction.