

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels							150			
EPA Site Specific Trigger Levels							150			
PM10-ST1-4/6/2009	Southwest Area (sidewalk bridge level)	4/6/09	1440	Particulate	Direct Read	Met One E-BAM	78	No	No	
PM10-ST2-4/6/2009	Southeast Area (sidewalk bridge level)	4/6/09	1440	Particulate	Direct Read	Met One E-BAM	42	No	No	
PM10-ST4-4/6/2009	Northwest Area (street-level)	4/6/09	1440	Particulate	Direct Read	Met One E-BAM	63	No	No	
PM10-ST5-4/6/2009	Firehouse #10 (roof level)	4/6/09	1440	Particulate	Direct Read	Met One E-BAM	44	No	No	
PM10-ST10-4/6/2009	North Side Sidewalk Bridge	4/6/09	1440	Particulate	Direct Read	Met One E-BAM	51	No	No	
PM10-ST100-4/6/2009	Station 10 Field Duplicate	4/6/09	1440	Particulate	Direct Read	Met One E-BAM	39	No	No	
PM10-ST11-4/6/2009	90 Trinity Place (roof level)	4/6/09	1440	Particulate	Direct Read	Met One E-BAM	35	No	No	
PM10-ST12-4/6/2009	110 Greenwich Street (roof level)	4/6/09	1440	Particulate	Direct Read	Met One E-BAM	62	No	No	
PM10-ST13-4/6/2009	Marriott Hotel, 38th Floor (roof level)	4/6/09	1440	Particulate	Direct Read	Met One E-BAM	63	No	No	
PM10-ST14-4/6/2009	West Face - South end at corner (scaffolding level)	4/6/09	1440	Particulate	Direct Read	Met One E-BAM	35	No	No	
PM10-ST15-4/6/2009	South Face - East end at corner (scaffolding level)	4/6/09	1440	Particulate	Direct Read	Met One E-BAM	33	No	No	
PM10-ST16-4/6/2009	East Face - North end at corner (scaffolding level)	4/6/09	1440	Particulate	Direct Read	Met One E-BAM	50	No	No	
PM10-ST17-4/6/2009	North Face - West end at corner (scaffolding level)	4/6/09	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST1-4/7/2009	Southwest Area (sidewalk bridge level)	4/7/09	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST2-4/7/2009	Southeast Area (sidewalk bridge level)	4/7/09	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST4-4/7/2009	Northwest Area (street-level)	4/7/09	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST5-4/7/2009	Firehouse #10 (roof level)	4/7/09	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST10-4/7/2009	North Side Sidewalk Bridge	4/7/09	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST100-4/7/2009	Station 10 Field Duplicate	4/7/09	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST11-4/7/2009	90 Trinity Place (roof level)	4/7/09	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM10-ST12-4/7/2009	110 Greenwich Street (roof level)	4/7/09	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM10-ST13-4/7/2009	Marriott Hotel, 38th Floor (roof level)	4/7/09	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST14-4/7/2009	West Face - South end at corner (scaffolding level)	4/7/09	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM10-ST15-4/7/2009	South Face - East end at corner (scaffolding level)	4/7/09	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	
PM10-ST16-4/7/2009	East Face - North end at corner (scaffolding level)	4/7/09	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	

Note:

1. The PM10 reading from Station 17 (North Face - West end at corner [scaffolding level]) on April 7, 2009 was not available on account of instrument malfunction.