

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
							150			
							150			
PM10-ST1-5/11/2009	Southwest Area (sidewalk bridge level)	5/11/09	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST2-5/11/2009	Southeast Area (sidewalk bridge level)	5/11/09	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST4-5/11/2009	Northwest Area (street-level)	5/11/09	1440	Particulate	Direct Read	Met One E-BAM	30	No	No	
PM10-ST5-5/11/2009	Firehouse #10 (roof level)	5/11/09	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST10-5/11/2009	North Side Sidewalk Bridge	5/11/09	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST100-5/11/2009	Station 10 Field Duplicate	5/11/09	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST11-5/11/2009	90 Trinity Place (roof level)	5/11/09	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST12-5/11/2009	110 Greenwich Street (roof level)	5/11/09	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST13-5/11/2009	Marriott Hotel, 38th Floor (roof level)	5/11/09	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST14-5/11/2009	West Face - South end at corner (scaffolding level)	5/11/09	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST15-5/11/2009	South Face - East end at corner (scaffolding level)	5/11/09	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST16-5/11/2009	East Face - North end at corner (scaffolding level)	5/11/09	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST17-5/11/2009	North Face - West end at corner (scaffolding level)	5/11/09	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST1-5/12/2009	Southwest Area (sidewalk bridge level)	5/12/09	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST2-5/12/2009	Southeast Area (sidewalk bridge level)	5/12/09	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM10-ST4-5/12/2009	Northwest Area (street-level)	5/12/09	1440	Particulate	Direct Read	Met One E-BAM	38	No	No	
PM10-ST5-5/12/2009	Firehouse #10 (roof level)	5/12/09	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST10-5/12/2009	North Side Sidewalk Bridge	5/12/09	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST100-5/12/2009	Station 10 Field Duplicate	5/12/09	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST11-5/12/2009	90 Trinity Place (roof level)	5/12/09	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST12-5/12/2009	110 Greenwich Street (roof level)	5/12/09	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST14-5/12/2009	West Face - South end at corner (scaffolding level)	5/12/09	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST15-5/12/2009	South Face - East end at corner (scaffolding level)	5/12/09	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST16-5/12/2009	East Face - North end at corner (scaffolding level)	5/12/09	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST17-5/12/2009	North Face - West end at corner (scaffolding level)	5/12/09	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	

Note:

1. The PM10 reading from Station 13 (Marriot Hotel, 38th Floor [roof level]) on May 12, 2009 was not available on account of instrument malfunction.