

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
							150			
							150			
PM10-ST1-7/11/2007	Southwest Area (sidewalk bridge level)	7/11/07	1440	Particulate	Direct Read	Met One E-BAM	62	No	No	
PM10-ST2-7/11/2007	Southeast Area (sidewalk bridge level)	7/11/07	1440	Particulate	Direct Read	Met One E-BAM	40	No	No	
PM10-ST4-7/11/2007	Northwest Area (street-level)	7/11/07	1440	Particulate	Direct Read	Met One E-BAM	40	No	No	
PM10-ST5-7/11/2007	Firehouse #10 (roof level)	7/11/07	1440	Particulate	Direct Read	Met One E-BAM	41	No	No	
PM10-ST10-7/11/2007	North Side Sidewalk Bridge	7/11/07	1440	Particulate	Direct Read	Met One E-BAM	39	No	No	
PM10-ST100-7/11/2007	Station 10 Field Duplicate	7/11/07	1440	Particulate	Direct Read	Met One E-BAM	42	No	No	
PM10-ST11-7/11/2007	90 Trinity Place (roof level)	7/11/07	1440	Particulate	Direct Read	Met One E-BAM	39	No	No	
PM10-ST12-7/11/2007	110 Greenwich Street (roof level)	7/11/07	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM10-ST13-7/11/2007	Marriott Hotel, 38th Floor (roof level)	7/11/07	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST14-7/11/2007	West Face - South end at corner (scaffolding level)	7/11/07	1440	Particulate	Direct Read	Met One E-BAM	32	No	No	
PM10-ST15-7/11/2007	South Face - East end at corner (scaffolding level)	7/11/07	1440	Particulate	Direct Read	Met One E-BAM	32	No	No	
PM10-ST16-7/11/2007	East Face - North end at corner (scaffolding level)	7/11/07	1440	Particulate	Direct Read	Met One E-BAM	39	No	No	
PM10-ST17-7/11/2007	North Face - West end at corner (scaffolding level)	7/11/07	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM10-ST1-7/12/2007	Southwest Area (sidewalk bridge level)	7/12/07	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST2-7/12/2007	Southeast Area (sidewalk bridge level)	7/12/07	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM10-ST4-7/12/2007	Northwest Area (street-level)	7/12/07	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST5-7/12/2007	Firehouse #10 (roof level)	7/12/07	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM10-ST10-7/12/2007	North Side Sidewalk Bridge	7/12/07	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST100-7/12/2007	Station 10 Field Duplicate	7/12/07	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST11-7/12/2007	90 Trinity Place (roof level)	7/12/07	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST12-7/12/2007	110 Greenwich Street (roof level)	7/12/07	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST13-7/12/2007	Marriott Hotel, 38th Floor (roof level)	7/12/07	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST14-7/12/2007	West Face - South end at corner (scaffolding level)	7/12/07	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST15-7/12/2007	South Face - East end at corner (scaffolding level)	7/12/07	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST16-7/12/2007	East Face - North end at corner (scaffolding level)	7/12/07	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	

Note:

1. The PM 10 reading at Station 17 (North Face - West end at corner [scaffolding level]) on July 12, 2007 was not available on account of instrument malfunction.