

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels							150			
EPA Site Specific Trigger Levels							150			
PM10-ST1-8/21/2009	Southwest Area (sidewalk bridge level)	8/21/09	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST2-8/21/2009	Southeast Area (sidewalk bridge level)	8/21/09	1440	Particulate	Direct Read	Met One E-BAM	40	No	No	
PM10-ST4-8/21/2009	Northwest Area (street-level)	8/21/09	1440	Particulate	Direct Read	Met One E-BAM	48	No	No	
PM10-ST5-8/21/2009	Firehouse #10 (roof level)	8/21/09	1440	Particulate	Direct Read	Met One E-BAM	31	No	No	
PM10-ST10-8/21/2009	North Side Sidewalk Bridge	8/21/09	1440	Particulate	Direct Read	Met One E-BAM	39	No	No	
PM10-ST100-8/21/2009	Station 10 Field Duplicate	8/21/09	1440	Particulate	Direct Read	Met One E-BAM	42	No	No	
PM10-ST11-8/21/2009	90 Trinity Place (roof level)	8/21/09	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST12-8/21/2009	110 Greenwich Street (roof level)	8/21/09	1440	Particulate	Direct Read	Met One E-BAM	30	No	No	
PM10-ST13-8/21/2009	Marriott Hotel, 38th Floor (roof level)	8/21/09	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST1-8/22/2009	Southwest Area (sidewalk bridge level)	8/22/09	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST2-8/22/2009	Southeast Area (sidewalk bridge level)	8/22/09	1440	Particulate	Direct Read	Met One E-BAM	38	No	No	
PM10-ST4-8/22/2009	Northwest Area (street-level)	8/22/09	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM10-ST5-8/22/2009	Firehouse #10 (roof level)	8/22/09	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST10-8/22/2009	North Side Sidewalk Bridge	8/22/09	1440	Particulate	Direct Read	Met One E-BAM	34	No	No	
PM10-ST100-8/22/2009	Station 10 Field Duplicate	8/22/09	1440	Particulate	Direct Read	Met One E-BAM	31	No	No	
PM10-ST11-8/22/2009	90 Trinity Place (roof level)	8/22/09	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM10-ST12-8/22/2009	110 Greenwich Street (roof level)	8/22/09	1440	Particulate	Direct Read	Met One E-BAM	32	No	No	
PM10-ST13-8/22/2009	Marriott Hotel, 38th Floor (roof level)	8/22/09	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM10-ST1-8/23/2009	Southwest Area (sidewalk bridge level)	8/23/09	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM10-ST2-8/23/2009	Southeast Area (sidewalk bridge level)	8/23/09	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM10-ST4-8/23/2009	Northwest Area (street-level)	8/23/09	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST5-8/23/2009	Firehouse #10 (roof level)	8/23/09	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST10-8/23/2009	North Side Sidewalk Bridge	8/23/09	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST100-8/23/2009	Station 10 Field Duplicate	8/23/09	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM10-ST11-8/23/2009	90 Trinity Place (roof level)	8/23/09	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST12-8/23/2009	110 Greenwich Street (roof level)	8/23/09	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST13-8/23/2009	Marriott Hotel, 38th Floor (roof level)	8/23/09	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	