

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
<b>Target Air Quality Levels</b>							<b>150</b>			
<b>EPA Site Specific Trigger Levels</b>							<b>150</b>			
PM10-ST1-9/12/2008	Southwest Area (sidewalk bridge level)	9/12/08	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM10-ST2-9/12/2008	Southeast Area (sidewalk bridge level)	9/12/08	1440	Particulate	Direct Read	Met One E-BAM	40	No	No	
PM10-ST4-9/12/2008	Northwest Area (street-level)	9/12/08	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM10-ST5-9/12/2008	Firehouse #10 (roof level)	9/12/08	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM10-ST10-9/12/2008	North Side Sidewalk Bridge	9/12/08	1440	Particulate	Direct Read	Met One E-BAM	34	No	No	
PM10-ST11-9/12/2008	90 Trinity Place (roof level)	9/12/08	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST12-9/12/2008	110 Greenwich Street (roof level)	9/12/08	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST13-9/12/2008	Marriott Hotel, 38th Floor (roof level)	9/12/08	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST14-9/12/2008	West Face - South end at corner (scaffolding level)	9/12/08	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM10-ST15-9/12/2008	South Face - East end at corner (scaffolding level)	9/12/08	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST16-9/12/2008	East Face - North end at corner (scaffolding level)	9/12/08	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM10-ST17-9/12/2008	North Face - West end at corner (scaffolding level)	9/12/08	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM10-ST1-9/13/2008	Southwest Area (sidewalk bridge level)	9/13/08	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM10-ST2-9/13/2008	Southeast Area (sidewalk bridge level)	9/13/08	1440	Particulate	Direct Read	Met One E-BAM	31	No	No	
PM10-ST4-9/13/2008	Northwest Area (street-level)	9/13/08	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM10-ST5-9/13/2008	Firehouse #10 (roof level)	9/13/08	1440	Particulate	Direct Read	Met One E-BAM	35	No	No	
PM10-ST10-9/13/2008	North Side Sidewalk Bridge	9/13/08	1440	Particulate	Direct Read	Met One E-BAM	32	No	No	
PM10-ST11-9/13/2008	90 Trinity Place (roof level)	9/13/08	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST12-9/13/2008	110 Greenwich Street (roof level)	9/13/08	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM10-ST13-9/13/2008	Marriott Hotel, 38th Floor (roof level)	9/13/08	1440	Particulate	Direct Read	Met One E-BAM	32	No	No	
PM10-ST14-9/13/2008	West Face - South end at corner (scaffolding level)	9/13/08	1440	Particulate	Direct Read	Met One E-BAM	34	No	No	
PM10-ST15-9/13/2008	South Face - East end at corner (scaffolding level)	9/13/08	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST16-9/13/2008	East Face - North end at corner (scaffolding level)	9/13/08	1440	Particulate	Direct Read	Met One E-BAM	42	No	No	
PM10-ST17-9/13/2008	North Face - West end at corner (scaffolding level)	9/13/08	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM10-ST1-9/14/2008	Southwest Area (sidewalk bridge level)	9/14/08	1440	Particulate	Direct Read	Met One E-BAM	32	No	No	
PM10-ST2-9/14/2008	Southeast Area (sidewalk bridge level)	9/14/08	1440	Particulate	Direct Read	Met One E-BAM	36	No	No	
PM10-ST4-9/14/2008	Northwest Area (street-level)	9/14/08	1440	Particulate	Direct Read	Met One E-BAM	35	No	No	
PM10-ST5-9/14/2008	Firehouse #10 (roof level)	9/14/08	1440	Particulate	Direct Read	Met One E-BAM	55	No	No	
PM10-ST10-9/14/2008	North Side Sidewalk Bridge	9/14/08	1440	Particulate	Direct Read	Met One E-BAM	36	No	No	
PM10-ST100-9/14/2008	Station 10 Field Duplicate	9/14/08	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM10-ST11-9/14/2008	90 Trinity Place (roof level)	9/14/08	1440	Particulate	Direct Read	Met One E-BAM	31	No	No	
PM10-ST12-9/14/2008	110 Greenwich Street (roof level)	9/14/08	1440	Particulate	Direct Read	Met One E-BAM	39	No	No	
PM10-ST13-9/14/2008	Marriott Hotel, 38th Floor (roof level)	9/14/08	1440	Particulate	Direct Read	Met One E-BAM	36	No	No	
PM10-ST14-9/14/2008	West Face - South end at corner (scaffolding level)	9/14/08	1440	Particulate	Direct Read	Met One E-BAM	31	No	No	
PM10-ST15-9/14/2008	South Face - East end at corner (scaffolding level)	9/14/08	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM10-ST16-9/14/2008	East Face - North end at corner (scaffolding level)	9/14/08	1440	Particulate	Direct Read	Met One E-BAM	30	No	No	
PM10-ST17-9/14/2008	North Face - West end at corner (scaffolding level)	9/14/08	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	

Note:

1. The PM10 readings from Station 100 (Station 10 Field Duplicate) on September 12 and 13, 2008 were not available on account of instrument malfunction.