

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
							150			
							150			
PM10-ST1-10/1/2010	Southwest Area (sidewalk bridge level)	10/1/10	1440	Particulate	Direct Read	Met One E-BAM	34	No	No	
PM10-ST2-10/1/2010	Southeast Area (sidewalk bridge level)	10/1/10	1440	Particulate	Direct Read	Met One E-BAM	55	No	No	
PM10-ST4-10/1/2010	Northwest Area (street-level)	10/1/10	1440	Particulate	Direct Read	Met One E-BAM	36	No	No	
PM10-ST5-10/1/2010	Firehouse #10 (roof level)	10/1/10	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST20-10/1/2010	Northeast Area, Sidewalk Bridge	10/1/10	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM10-ST200-10/1/2010	Station 20 Field Duplicate	10/1/10	1440	Particulate	Direct Read	Met One E-BAM	30	No	No	
PM10-ST21-10/1/2010	Marriott Hotel, 4th Floor	10/1/10	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM10-ST22-10/1/2010	Roof of 120 Cedar Street	10/1/10	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST1-10/2/2010	Southwest Area (sidewalk bridge level)	10/2/10	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM10-ST2-10/2/2010	Southeast Area (sidewalk bridge level)	10/2/10	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST4-10/2/2010	Northwest Area (street-level)	10/2/10	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST5-10/2/2010	Firehouse #10 (roof level)	10/2/10	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST20-10/2/2010	Northeast Area, Sidewalk Bridge	10/2/10	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST200-10/2/2010	Station 20 Field Duplicate	10/2/10	1440	Particulate	Direct Read	Met One E-BAM	32	No	No	
PM10-ST21-10/2/2010	Marriott Hotel, 4th Floor	10/2/10	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST22-10/2/2010	Roof of 120 Cedar Street	10/2/10	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST1-10/3/2010	Southwest Area (sidewalk bridge level)	10/3/10	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST2-10/3/2010	Southeast Area (sidewalk bridge level)	10/3/10	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST4-10/3/2010	Northwest Area (street-level)	10/3/10	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST5-10/3/2010	Firehouse #10 (roof level)	10/3/10	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST20-10/3/2010	Northeast Area, Sidewalk Bridge	10/3/10	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST200-10/3/2010	Station 20 Field Duplicate	10/3/10	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST21-10/3/2010	Marriott Hotel, 4th Floor	10/3/10	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST22-10/3/2010	Roof of 120 Cedar Street	10/3/10	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	