

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels							150			
EPA Site Specific Trigger Levels							150			
PM10-ST1-10/2/2009	Southwest Area (sidewalk bridge)	10/2/09	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM10-ST2-10/2/2009	Southeast Area (sidewalk bridge)	10/2/09	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM10-ST4-10/2/2009	Northwest Area (street-level)	10/2/09	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM10-ST5-10/2/2009	Firehouse #10 (roof level)	10/2/09	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST10-10/2/2009	North Side Sidewalk Bridge	10/2/09	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM10-ST100-10/2/2009	Station 10 Field Duplicate	10/2/09	1440	Particulate	Direct Read	Met One E-BAM	32	No	No	
PM10-ST11-10/2/2009	90 Trinity Place (roof level)	10/2/09	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST12-10/2/2009	110 Greenwich Street (roof level)	10/2/09	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST13-10/2/2009	Marriott Hotel, 38th Floor (roof level)	10/2/09	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST1-10/3/2009	Southwest Area (sidewalk bridge)	10/3/09	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM10-ST2-10/3/2009	Southeast Area (sidewalk bridge)	10/3/09	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM10-ST4-10/3/2009	Northwest Area (street-level)	10/3/09	1440	Particulate	Direct Read	Met One E-BAM	30	No	No	
PM10-ST5-10/3/2009	Firehouse #10 (roof level)	10/3/09	1440	Particulate	Direct Read	Met One E-BAM	35	No	No	
PM10-ST10-10/3/2009	North Side Sidewalk Bridge	10/3/09	1440	Particulate	Direct Read	Met One E-BAM	31	No	No	
PM10-ST100-10/3/2009	Station 10 Field Duplicate	10/3/09	1440	Particulate	Direct Read	Met One E-BAM	33	No	No	
PM10-ST11-10/3/2009	90 Trinity Place (roof level)	10/3/09	1440	Particulate	Direct Read	Met One E-BAM	36	No	No	
PM10-ST12-10/3/2009	110 Greenwich Street (roof level)	10/3/09	1440	Particulate	Direct Read	Met One E-BAM	37	No	No	
PM10-ST13-10/3/2009	Marriott Hotel, 38th Floor (roof level)	10/3/09	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST1-10/4/2009	Southwest Area (sidewalk bridge)	10/4/09	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST2-10/4/2009	Southeast Area (sidewalk bridge)	10/4/09	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM10-ST4-10/4/2009	Northwest Area (street-level)	10/4/09	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST5-10/4/2009	Firehouse #10 (roof level)	10/4/09	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM10-ST10-10/4/2009	North Side Sidewalk Bridge	10/4/09	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM10-ST100-10/4/2009	Station 10 Field Duplicate	10/4/09	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM10-ST11-10/4/2009	90 Trinity Place (roof level)	10/4/09	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST12-10/4/2009	110 Greenwich Street (roof level)	10/4/09	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM10-ST13-10/4/2009	Marriott Hotel, 38th Floor (roof level)	10/4/09	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	