

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels							150			
EPA Site Specific Trigger Levels							150			
PM10-ST1-10/11/2010	Southwest Area (sidewalk bridge level)	10/11/10	1440	Particulate	Direct Read	Met One E-BAM	42	No	No	
PM10-ST2-10/11/2010	Southeast Area (sidewalk bridge level)	10/11/10	1140	Particulate	Direct Read	Met One E-BAM	23	No	No	Note 1
PM10-ST4-10/11/2010	Northwest Area (street-level)	10/11/10	1440	Particulate	Direct Read	Met One E-BAM	51	No	No	
PM10-ST5-10/11/2010	Firehouse #10 (roof level)	10/11/10	1440	Particulate	Direct Read	Met One E-BAM	47	No	No	
PM10-ST20-10/11/2010	Northeast Area, Sidewalk Bridge	10/11/10	1440	Particulate	Direct Read	Met One E-BAM	41	No	No	
PM10-ST200-10/11/2010	Station 20 Field Duplicate	10/11/10	1440	Particulate	Direct Read	Met One E-BAM	47	No	No	
PM10-ST21-10/11/2010	Marriott Hotel, 4th Floor	10/11/10	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM10-ST22-10/11/2010	Roof of 120 Cedar Street	10/11/10	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM10-ST1-10/12/2010	Southwest Area (sidewalk bridge level)	10/12/10	1440	Particulate	Direct Read	Met One E-BAM	40	No	No	
PM10-ST2-10/12/2010	Southeast Area (sidewalk bridge level)	10/12/10	570	Particulate	Direct Read	Met One E-BAM	37	No	No	Note 2
PM10-ST4-10/12/2010	Northwest Area (street-level)	10/12/10	1440	Particulate	Direct Read	Met One E-BAM	57	No	No	
PM10-ST5-10/12/2010	Firehouse #10 (roof level)	10/12/10	1440	Particulate	Direct Read	Met One E-BAM	30	No	No	
PM10-ST20-10/12/2010	Northeast Area, Sidewalk Bridge	10/12/10	1440	Particulate	Direct Read	Met One E-BAM	31	No	No	
PM10-ST200-10/12/2010	Station 20 Field Duplicate	10/12/10	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST21-10/12/2010	Marriott Hotel, 4th Floor	10/12/10	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST22-10/12/2010	Roof of 120 Cedar Street	10/12/10	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	

Note:

1. The PM10 reading from Station 2 (Southeast Area [sidewalk bridge level]) on October 11, 2010 represents a partial average from 0000 to 1900 due to instrument failure; the daily average represents 79% of the 24 hour data set.
2. The PM10 reading from Station 2 (Southeast Area [sidewalk bridge level]) on October 12, 2010 represents a partial average from 1430 to 2400 due to instrument failure; the daily average represents 40% of the 24 hour data set.