

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
							150			
							150			
Target Air Quality Levels										
EPA Site Specific Trigger Levels										
PM10-ST1-10/17/2008	Southwest Area (sidewalk bridge level)	10/17/08	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST2-10/17/2008	Southeast Area (sidewalk bridge level)	10/17/08	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM10-ST4-10/17/2008	Northwest Area (street-level)	10/17/08	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST5-10/17/2008	Firehouse #10 (roof level)	10/17/08	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM10-ST10-10/17/2008	North Side Sidewalk Bridge	10/17/08	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST100-10/17/2008	Station 10 Field Duplicate	10/17/08	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST11-10/17/2008	90 Trinity Place (roof level)	10/17/08	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST12-10/17/2008	110 Greenwich Street (roof level)	10/17/08	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST13-10/17/2008	Marriott Hotel, 38th Floor (roof level)	10/17/08	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST14-10/17/2008	West Face - South end at corner (scaffolding level)	10/17/08	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST15-10/17/2008	South Face - East end at corner (scaffolding level)	10/17/08	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST16-10/17/2008	East Face - North end at corner (scaffolding level)	10/17/08	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST17-10/17/2008	North Face - West end at corner (scaffolding level)	10/17/08	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST1-10/18/2008	Southwest Area (sidewalk bridge level)	10/18/08	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST2-10/18/2008	Southeast Area (sidewalk bridge level)	10/18/08	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM10-ST5-10/18/2008	Firehouse #10 (roof level)	10/18/08	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST10-10/18/2008	North Side Sidewalk Bridge	10/18/08	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST100-10/18/2008	Station 10 Field Duplicate	10/18/08	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST11-10/18/2008	90 Trinity Place (roof level)	10/18/08	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST12-10/18/2008	110 Greenwich Street (roof level)	10/18/08	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST13-10/18/2008	Marriott Hotel, 38th Floor (roof level)	10/18/08	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST14-10/18/2008	West Face - South end at corner (scaffolding level)	10/18/08	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST15-10/18/2008	South Face - East end at corner (scaffolding level)	10/18/08	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST16-10/18/2008	East Face - North end at corner (scaffolding level)	10/18/08	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST17-10/18/2008	North Face - West end at corner (scaffolding level)	10/18/08	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST1-10/19/2008	Southwest Area (sidewalk bridge level)	10/19/08	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST2-10/19/2008	Southeast Area (sidewalk bridge level)	10/19/08	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST4-10/19/2008	Northwest Area (street-level)	10/19/08	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST5-10/19/2008	Firehouse #10 (roof level)	10/19/08	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST10-10/19/2008	North Side Sidewalk Bridge	10/19/08	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST100-10/19/2008	Station 10 Field Duplicate	10/19/08	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST11-10/19/2008	90 Trinity Place (roof level)	10/19/08	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST12-10/19/2008	110 Greenwich Street (roof level)	10/19/08	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST13-10/19/2008	Marriott Hotel, 38th Floor (roof level)	10/19/08	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST14-10/19/2008	West Face - South end at corner (scaffolding level)	10/19/08	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST15-10/19/2008	South Face - East end at corner (scaffolding level)	10/19/08	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM10-ST16-10/19/2008	East Face - North end at corner (scaffolding level)	10/19/08	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST17-10/19/2008	North Face - West end at corner (scaffolding level)	10/19/08	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	

Note:

1. The PM2.5 reading at Station 4 (Northwest Area [street-level]) on October 18, 2008 was not available on account of power failure.