

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels							150			
EPA Site Specific Trigger Levels							150			
PM10-ST1-11/13/2005	Southwest Area (street-level)	11/13/05	1440	Particulate	Direct Read	Met One E-BAM	23.4	No	No	
PM10-ST2-11/13/2005	Southeast Area (sidewalk bridge level)	11/13/05	1440	Particulate	Direct Read	Met One E-BAM	33.8	No	No	
PM10-ST4-11/13/2005	Northwest Area (street-level)	11/13/05	1440	Particulate	Direct Read	Met One E-BAM	23.4	No	No	
PM10-ST5-11/13/2005	Firehouse #10 (roof level)	11/13/05	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST10-11/13/2005	North Side Sidewalk Bridge	11/13/05	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST100-11/13/2005	Station 10 Field Duplicate	11/13/05	1440	Particulate	Direct Read	Met One E-BAM	24.7	No	No	
PM10-ST11-11/13/2005	90 Trinity Place (roof level)	11/13/05	1440	Particulate	Direct Read	Met One E-BAM	28.6	No	No	
PM10-ST12-11/13/2005	110 Greenwich Street (roof level)	11/13/05	1440	Particulate	Direct Read	Met One E-BAM	23.4	No	No	
PM10-ST13-11/13/2005	Marriott Hotel, 38th Floor (roof level)	11/13/05	1440	Particulate	Direct Read	Met One E-BAM	20.8	No	No	
PM10-ST1-11/14/2005	Southwest Area (street-level)	11/14/05	1440	Particulate	Direct Read	Met One E-BAM	22.1	No	No	
PM10-ST2-11/14/2005	Southeast Area (sidewalk bridge level)	11/14/05	1440	Particulate	Direct Read	Met One E-BAM	36.4	No	No	
PM10-ST4-11/14/2005	Northwest Area (street-level)	11/14/05	1440	Particulate	Direct Read	Met One E-BAM	23.4	No	No	
PM10-ST5-11/14/2005	Firehouse #10 (roof level)	11/14/05	1440	Particulate	Direct Read	Met One E-BAM	19.5	No	No	
PM10-ST10-11/14/2005	North Side Sidewalk Bridge	11/14/05	1440	Particulate	Direct Read	Met One E-BAM	20.8	No	No	
PM10-ST100-11/14/2005	Station 10 Field Duplicate	11/14/05	1440	Particulate	Direct Read	Met One E-BAM	19.5	No	No	
PM10-ST11-11/14/2005	90 Trinity Place (roof level)	11/14/05	1440	Particulate	Direct Read	Met One E-BAM	23.4	No	No	
PM10-ST12-11/14/2005	110 Greenwich Street (roof level)	11/14/05	1440	Particulate	Direct Read	Met One E-BAM	19.5	No	No	
PM10-ST13-11/14/2005	Marriott Hotel, 38th Floor (roof level)	11/14/05	1440	Particulate	Direct Read	Met One E-BAM	16.9	No	No	
PM10-ST1-11/15/2005	Southwest Area (street-level)	11/15/05	1440	Particulate	Direct Read	Met One E-BAM	37.7	No	No	
PM10-ST2-11/15/2005	Southeast Area (sidewalk bridge level)	11/15/05	1440	Particulate	Direct Read	Met One E-BAM	49.4	No	No	
PM10-ST4-11/15/2005	Northwest Area (street-level)	11/15/05	1440	Particulate	Direct Read	Met One E-BAM	35.1	No	No	
PM10-ST5-11/15/2005	Firehouse #10 (roof level)	11/15/05	1440	Particulate	Direct Read	Met One E-BAM	31.2	No	No	
PM10-ST10-11/15/2005	North Side Sidewalk Bridge	11/15/05	1440	Particulate	Direct Read	Met One E-BAM	32.5	No	No	
PM10-ST100-11/15/2005	Station 10 Field Duplicate	11/15/05	1440	Particulate	Direct Read	Met One E-BAM	31.2	No	No	
PM10-ST11-11/15/2005	90 Trinity Place (roof level)	11/15/05	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST12-11/15/2005	110 Greenwich Street (roof level)	11/15/05	1440	Particulate	Direct Read	Met One E-BAM	32.5	No	No	
PM10-ST13-11/15/2005	Marriott Hotel, 38th Floor (roof level)	11/15/05	1440	Particulate	Direct Read	Met One E-BAM	29.9	No	No	
PM10-ST1-11/16/2005	Southwest Area (street-level)	11/16/05	1440	Particulate	Direct Read	Met One E-BAM	39	No	No	
PM10-ST2-11/16/2005	Southeast Area (sidewalk bridge level)	11/16/05	1440	Particulate	Direct Read	Met One E-BAM	58.5	No	No	
PM10-ST4-11/16/2005	Northwest Area (street-level)	11/16/05	1440	Particulate	Direct Read	Met One E-BAM	40.3	No	No	
PM10-ST5-11/16/2005	Firehouse #10 (roof level)	11/16/05	1440	Particulate	Direct Read	Met One E-BAM	44.2	No	No	
PM10-ST10-11/16/2005	North Side Sidewalk Bridge	11/16/05	1440	Particulate	Direct Read	Met One E-BAM	45.5	No	No	
PM10-ST100-11/16/2005	Station 10 Field Duplicate	11/16/05	1440	Particulate	Direct Read	Met One E-BAM	29.9	No	No	
PM10-ST11-11/16/2005	90 Trinity Place (roof level)	11/16/05	1440	Particulate	Direct Read	Met One E-BAM	23.4	No	No	
PM10-ST12-11/16/2005	110 Greenwich Street (roof level)	11/16/05	1440	Particulate	Direct Read	Met One E-BAM	48.1	No	No	
PM10-ST13-11/16/2005	Marriott Hotel, 38th Floor (roof level)	11/16/05	1440	Particulate	Direct Read	Met One E-BAM	36.4	No	No	