TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target	Exceeds EPA	
Target Air Quality Levels							150	Air Quality	Site Specific	Comments
EPA Site Specific Trigger Levels							150	Levels	Trigger Levels	
PM10-ST1-11/13/2009	Southwest Area (sidewalk bridge level)	11/13/09	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST2-11/13/2009	Southeast Area (sidewalk bridge level)	11/13/09	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST4-11/13/2009	Northwest Area (street-level)	11/13/09	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM10-ST5-11/13/2009	Firehouse #10 (roof level)	11/13/09	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM10-ST10-11/13/2009	North Side Sidewalk Bridge	11/13/09	1440	Particulate	Direct Read	Met One E-BAM	38	No	No	
PM10-ST100-11/13/2009	Station 10 Field Duplicate	11/13/09	1440	Particulate	Direct Read	Met One E-BAM	41	No	No	
PM10-ST11-11/13/2009	90 Trinity Place (roof level)	11/13/09	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST12-11/13/2009	110 Greenwich Street (roof level)	11/13/09	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST13-11/13/2009	Marriott Hotel, 38th Floor (roof level)	11/13/09	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST1-11/14/2009	Southwest Area (sidewalk bridge level)	11/14/09	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST2-11/14/2009	Southeast Area (sidewalk bridge level)	11/14/09	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST4-11/14/2009	Northwest Area (street-level)	11/14/09	1440	Particulate	Direct Read	Met One E-BAM	31	No	No	
PM10-ST5-11/14/2009	Firehouse #10 (roof level)	11/14/09	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST10-11/14/2009	North Side Sidewalk Bridge	11/14/09	1440	Particulate	Direct Read	Met One E-BAM	37	No	No	
PM10-ST100-11/14/2009	Station 10 Field Duplicate	11/14/09	1440	Particulate	Direct Read	Met One E-BAM	35	No	No	
PM10-ST11-11/14/2009	90 Trinity Place (roof level)	11/14/09	1440	Particulate	Direct Read	Met One E-BAM	30	No	No	
PM10-ST12-11/14/2009	110 Greenwich Street (roof level)	11/14/09	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST13-11/14/2009	Marriott Hotel, 38th Floor (roof level)	11/14/09	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST1-11/15/2009	Southwest Area (sidewalk bridge level)	11/15/09	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST2-11/15/2009	Southeast Area (sidewalk bridge level)	11/15/09	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST4-11/15/2009	Northwest Area (street-level)	11/15/09	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST5-11/15/2009	Firehouse #10 (roof level)	11/15/09	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST10-11/15/2009	North Side Sidewalk Bridge	11/15/09	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST100-11/15/2009	Station 10 Field Duplicate	11/15/09	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM10-ST11-11/15/2009	90 Trinity Place (roof level)	11/15/09	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST12-11/15/2009	110 Greenwich Street (roof level)	11/15/09	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST13-11/15/2009	Marriott Hotel, 38th Floor (roof level)	11/15/09	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	