

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
							150			
							150			
Target Air Quality Levels										
EPA Site Specific Trigger Levels										
PM10-ST1-11/20/2005	Southwest Area (street-level)	11/20/05	1440	Particulate	Direct Read	Met One E-BAM	29.9	No	No	
PM10-ST2-11/20/2005	Southeast Area (sidewalk bridge level)	11/20/05	1440	Particulate	Direct Read	Met One E-BAM	41.6	No	No	
PM10-ST4-11/20/2005	Northwest Area (street-level)	11/20/05	1440	Particulate	Direct Read	Met One E-BAM	26.0	No	No	
PM10-ST5-11/20/2005	Firehouse #10 (roof level)	11/20/05	1440	Particulate	Direct Read	Met One E-BAM	31.2	No	No	
PM10-ST10-11/20/2005	North Side Sidewalk Bridge	11/20/05	1440	Particulate	Direct Read	Met One E-BAM	33.8	No	No	
PM10-ST100-11/20/2005	Station 10 Field Duplicate	11/20/05	1440	Particulate	Direct Read	Met One E-BAM	28.6	No	No	
PM10-ST11-11/20/2005	90 Trinity Place (roof level)	11/20/05	1440	Particulate	Direct Read	Met One E-BAM	32.5	No	No	
PM10-ST12-11/20/2005	110 Greenwich Street (roof level)	11/20/05	1440	Particulate	Direct Read	Met One E-BAM	27.3	No	No	
PM10-ST13-11/20/2005	Marriott Hotel, 38th Floor (roof level)	11/20/05	1440	Particulate	Direct Read	Met One E-BAM	24.7	No	No	
PM10-ST14-11/20/2005	West Face - South end at corner (scaffolding level)	11/20/05	1440	Particulate	Direct Read	Met One E-BAM	31.2	No	No	
PM10-ST15-11/20/2005	South Face - East end at corner (scaffolding level)	11/20/05	1440	Particulate	Direct Read	Met One E-BAM	29.9	No	No	
PM10-ST16-11/20/2005	East Face - North end at corner (scaffolding level)	11/20/05	1440	Particulate	Direct Read	Met One E-BAM	26.0	No	No	
PM10-ST17-11/20/2005	North Face - West end at corner (scaffolding level)	11/20/05	1440	Particulate	Direct Read	Met One E-BAM	27.3	No	No	
PM10-ST1-11/21/2005	Southwest Area (street-level)	11/21/05	1440	Particulate	Direct Read	Met One E-BAM	51	No	No	
PM10-ST2-11/21/2005	Southeast Area (sidewalk bridge level)	11/21/05	1440	Particulate	Direct Read	Met One E-BAM	56	No	No	
PM10-ST4-11/21/2005	Northwest Area (street-level)	11/21/05	1440	Particulate	Direct Read	Met One E-BAM	50	No	No	
PM10-ST5-11/21/2005	Firehouse #10 (roof level)	11/21/05	1440	Particulate	Direct Read	Met One E-BAM	54	No	No	
PM10-ST10-11/21/2005	North Side Sidewalk Bridge	11/21/05	1440	Particulate	Direct Read	Met One E-BAM	48	No	No	
PM10-ST100-11/21/2005	Station 10 Field Duplicate	11/21/05	1440	Particulate	Direct Read	Met One E-BAM	46	No	No	
PM10-ST11-11/21/2005	90 Trinity Place (roof level)	11/21/05	1440	Particulate	Direct Read	Met One E-BAM	39	No	No	
PM10-ST12-11/21/2005	110 Greenwich Street (roof level)	11/21/05	1440	Particulate	Direct Read	Met One E-BAM	41	No	No	
PM10-ST13-11/21/2005	Marriott Hotel, 38th Floor (roof level)	11/21/05	1440	Particulate	Direct Read	Met One E-BAM	37	No	No	
PM10-ST14-11/21/2005	West Face - South end at corner (scaffolding level)	11/21/05	1440	Particulate	Direct Read	Met One E-BAM	45	No	No	
PM10-ST15-11/21/2005	South Face - East end at corner (scaffolding level)	11/21/05	1440	Particulate	Direct Read	Met One E-BAM	36	No	No	
PM10-ST16-11/21/2005	East Face - North end at corner (scaffolding level)	11/21/05	1440	Particulate	Direct Read	Met One E-BAM	33	No	No	
PM10-ST17-11/21/2005	North Face - West end at corner (scaffolding level)	11/21/05	1440	Particulate	Direct Read	Met One E-BAM	33	No	No	
PM10-ST1-11/22/2005	Southwest Area (street-level)	11/22/05	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST2-11/22/2005	Southeast Area (sidewalk bridge level)	11/22/05	1440	Particulate	Direct Read	Met One E-BAM	34	No	No	
PM10-ST4-11/22/2005	Northwest Area (street-level)	11/22/05	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST5-11/22/2005	Firehouse #10 (roof level)	11/22/05	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST10-11/22/2005	North Side Sidewalk Bridge	11/22/05	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST100-11/22/2005	Station 10 Field Duplicate	11/22/05	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST11-11/22/2005	90 Trinity Place (roof level)	11/22/05	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST12-11/22/2005	110 Greenwich Street (roof level)	11/22/05	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST13-11/22/2005	Marriott Hotel, 38th Floor (roof level)	11/22/05	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST14-11/22/2005	West Face - South end at corner (scaffolding level)	11/22/05	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST15-11/22/2005	South Face - East end at corner (scaffolding level)	11/22/05	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST16-11/22/2005	East Face - North end at corner (scaffolding level)	11/22/05	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM10-ST17-11/22/2005	North Face - West end at corner (scaffolding level)	11/22/05	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	

Note: A correction factor of 1.30 was applied to the reported data on November 20, 2005. As directed by the EPA, no correction factor will be applied as of November 21, 2005.

TRC dispensed with use of correction factor commencing with data collected on November 21 2005. EPA agreed with elimination of correction factors as a result of a November 18 2005 telecom on this subject