

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels							150			
EPA Site Specific Trigger Levels							150			
PM10-ST1-12/30/2005	Southwest Area (sidewalk bridge level)	12/30/05	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM10-ST2-12/30/2005	Southeast Area (sidewalk bridge level)	12/30/05	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM10-ST4-12/30/2005	Northwest Area (street-level)	12/30/05	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM10-ST5-12/30/2005	Firehouse #10 (roof level)	12/30/05	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST10-12/30/2005	North Side Sidewalk Bridge	12/30/05	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST100-12/30/2005	Station 10 Field Duplicate	12/30/05	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST11-12/30/2005	90 Trinity Place (roof level)	12/30/05	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST12-12/30/2005	110 Greenwich Street (roof level)	12/30/05	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST13-12/30/2005	Marriott Hotel, 38th Floor (roof level)	12/30/05	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST14-12/30/2005	West Face - South end at corner (scaffolding level)	12/30/05	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST15-12/30/2005	South Face - East end at corner (scaffolding level)	12/30/05	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST16-12/30/2005	East Face - North end at corner (scaffolding level)	12/30/05	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	
PM10-ST17-12/30/2005	North Face - West end at corner (scaffolding level)	12/30/05	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST1-12/31/2005	Southwest Area (sidewalk bridge level)	12/31/05	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST2-12/31/2005	Southeast Area (sidewalk bridge level)	12/31/05	1440	Particulate	Direct Read	Met One E-BAM	41	No	No	
PM10-ST4-12/31/2005	Northwest Area (street-level)	12/31/05	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST5-12/31/2005	Firehouse #10 (roof level)	12/31/05	1440	Particulate	Direct Read	Met One E-BAM	33	No	No	
PM10-ST10-12/31/2005	North Side Sidewalk Bridge	12/31/05	1440	Particulate	Direct Read	Met One E-BAM	33	No	No	
PM10-ST100-12/31/2005	Station 10 Field Duplicate	12/31/05	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM10-ST11-12/31/2005	90 Trinity Place (roof level)	12/31/05	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM10-ST12-12/31/2005	110 Greenwich Street (roof level)	12/31/05	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST13-12/31/2005	Marriott Hotel, 38th Floor (roof level)	12/31/05	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST14-12/31/2005	West Face - South end at corner (scaffolding level)	12/31/05	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST15-12/31/2005	South Face - East end at corner (scaffolding level)	12/31/05	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST16-12/31/2005	East Face - North end at corner (scaffolding level)	12/31/05	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST17-12/31/2005	North Face - West end at corner (scaffolding level)	12/31/05	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	