

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
							150			
							150			
<b>Target Air Quality Levels</b>										
<b>EPA Site Specific Trigger Levels</b>										
PM10-ST1-12/31/2008	Southwest Area (sidewalk bridge level)	12/31/08	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST2-12/31/2008	Southeast Area (sidewalk bridge level)	12/31/08	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST4-12/31/2008	Northwest Area (street-level)	12/31/08	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST5-12/31/2008	Firehouse #10 (roof level)	12/31/08	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM10-ST10-12/31/2008	North Side Sidewalk Bridge	12/31/08	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST100-12/31/2008	Station 10 Field Duplicate	12/31/08	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST11-12/31/2008	90 Trinity Place (roof level)	12/31/08	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST12-12/31/2008	110 Greenwich Street (roof level)	12/31/08	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST13-12/31/2008	Marriott Hotel, 38th Floor (roof level)	12/31/08	1440	Particulate	Direct Read	Met One E-BAM	30	No	No	
PM10-ST14-12/31/2008	West Face - South end at corner (scaffolding level)	12/31/08	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST16-12/31/2008	East Face - North end at corner (scaffolding level)	12/31/08	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST17-12/31/2008	North Face - West end at corner (scaffolding level)	12/31/08	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM10-ST1-1/1/2009	Southwest Area (sidewalk bridge level)	1/1/09	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM10-ST2-1/1/2009	Southeast Area (sidewalk bridge level)	1/1/09	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST4-1/1/2009	Northwest Area (street-level)	1/1/09	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM10-ST5-1/1/2009	Firehouse #10 (roof level)	1/1/09	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM10-ST10-1/1/2009	North Side Sidewalk Bridge	1/1/09	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM10-ST100-1/1/2009	Station 10 Field Duplicate	1/1/09	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM10-ST11-1/1/2009	90 Trinity Place (roof level)	1/1/09	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST12-1/1/2009	110 Greenwich Street (roof level)	1/1/09	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST13-1/1/2009	Marriott Hotel, 38th Floor (roof level)	1/1/09	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST14-1/1/2009	West Face - South end at corner (scaffolding level)	1/1/09	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM10-ST15-1/1/2009	South Face - East end at corner (scaffolding level)	1/1/09	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST16-1/1/2009	East Face - North end at corner (scaffolding level)	1/1/09	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST17-1/1/2009	North Face - West end at corner (scaffolding level)	1/1/09	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	

Note:

1. The PM10 reading from Station 15 (South Face - East end at corner [scaffolding level]) on December 31, 2008 was not available on account of instrument malfunction.