

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM2.5 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels							40			
EPA Site Specific Trigger Levels							65			
PM2.5-ST1-1/8/2006	Southwest Area (sidewalk bridge level)	1/8/06	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM2.5-ST2-1/8/2006	Southeast Area (sidewalk bridge level)	1/8/06	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM2.5-ST4-1/8/2006	Northwest Area (street-level)	1/8/06	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM2.5-ST5-1/8/2006	Firehouse #10 (roof level)	1/8/06	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM2.5-ST10-1/8/2006	North Side Sidewalk Bridge	1/8/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM2.5-ST100-1/8/2006	Station 10 Field Duplicate	1/8/06	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST11-1/8/2006	90 Trinity Place (roof level)	1/8/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM2.5-ST12-1/8/2006	110 Greenwich Street (roof level)	1/8/06	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM2.5-ST13-1/8/2006	Marriott Hotel, 38th Floor (roof level)	1/8/06	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM2.5-ST14-1/8/2006	West Face - South end at corner (scaffolding level)	1/8/06	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM2.5-ST15-1/8/2006	South Face - East end at corner (scaffolding level)	1/8/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM2.5-ST16-1/8/2006	East Face - North end at corner (scaffolding level)	1/8/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM2.5-ST17-1/8/2006	North Face - West end at corner (scaffolding level)	1/8/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM2.5-ST1-1/9/2006	Southwest Area (sidewalk bridge level)	1/9/06	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM2.5-ST2-1/9/2006	Southeast Area (sidewalk bridge level)	1/9/06	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM2.5-ST4-1/9/2006	Northwest Area (street-level)	1/9/06	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM2.5-ST5-1/9/2006	Firehouse #10 (roof level)	1/9/06	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM2.5-ST10-1/9/2006	North Side Sidewalk Bridge	1/9/06	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM2.5-ST100-1/9/2006	Station 10 Field Duplicate	1/9/06	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM2.5-ST11-1/9/2006	90 Trinity Place (roof level)	1/9/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM2.5-ST12-1/9/2006	110 Greenwich Street (roof level)	1/9/06	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST13-1/9/2006	Marriott Hotel, 38th Floor (roof level)	1/9/06	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM2.5-ST14-1/9/2006	West Face - South end at corner (scaffolding level)	1/9/06	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST15-1/9/2006	South Face - East end at corner (scaffolding level)	1/9/06	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM2.5-ST16-1/9/2006	East Face - North end at corner (scaffolding level)	1/9/06	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM2.5-ST17-1/9/2006	North Face - West end at corner (scaffolding level)	1/9/06	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	