

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM2.5 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
<b>Target Air Quality Levels</b>							<b>40</b>			
<b>EPA Site Specific Trigger Levels</b>							<b>65</b>			
PM2.5-ST1-1/25/2006	Southwest Area (sidewalk bridge level)	1/25/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM2.5-ST2-1/25/2006	Southeast Area (sidewalk bridge level)	1/25/06	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM2.5-ST4-1/25/2006	Northwest Area (street-level)	1/25/06	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST5-1/25/2006	Firehouse #10 (roof level)	1/25/06	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM2.5-ST10-1/25/2006	North Side Sidewalk Bridge	1/25/06	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM2.5-ST100-1/25/2006	Station 10 Field Duplicate	1/25/06	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM2.5-ST11-1/25/2006	90 Trinity Place (roof level)	1/25/06	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM2.5-ST12-1/25/2006	110 Greenwich Street (roof level)	1/25/06	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM2.5-ST13-1/25/2006	Marriott Hotel, 38th Floor (roof level)	1/25/06	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM2.5-ST14-1/25/2006	West Face - South end at corner (scaffolding level)	1/25/06	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM2.5-ST15-1/25/2006	South Face - East end at corner (scaffolding level)	1/25/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM2.5-ST16-1/25/2006	East Face - North end at corner (scaffolding level)	1/25/06	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM2.5-ST17-1/25/2006	North Face - West end at corner (scaffolding level)	1/25/06	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM2.5-ST1-1/26/2006	Southwest Area (sidewalk bridge level)	1/26/06	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST2-1/26/2006	Southeast Area (sidewalk bridge level)	1/26/06	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST4-1/26/2006	Northwest Area (street-level)	1/26/06	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM2.5-ST5-1/26/2006	Firehouse #10 (roof level)	1/26/06	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM2.5-ST10-1/26/2006	North Side Sidewalk Bridge	1/26/06	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	
PM2.5-ST100-1/26/2006	Station 10 Field Duplicate	1/26/06	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	
PM2.5-ST11-1/26/2006	90 Trinity Place (roof level)	1/26/06	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	
PM2.5-ST12-1/26/2006	110 Greenwich Street (roof level)	1/26/06	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM2.5-ST13-1/26/2006	Marriott Hotel, 38th Floor (roof level)	1/26/06	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM2.5-ST14-1/26/2006	West Face - South end at corner (scaffolding level)	1/26/06	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM2.5-ST15-1/26/2006	South Face - East end at corner (scaffolding level)	1/26/06	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM2.5-ST16-1/26/2006	East Face - North end at corner (scaffolding level)	1/26/06	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	
PM2.5-ST17-1/26/2006	North Face - West end at corner (scaffolding level)	1/26/06	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	