

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM2.5 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels							40			
EPA Site Specific Trigger Levels							65			
PM2.5-ST1-2/1/2006	Southwest Area (sidewalk bridge level)	2/1/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM2.5-ST2-2/1/2006	Southeast Area (sidewalk bridge level)	2/1/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM2.5-ST4-2/1/2006	Northwest Area (street-level)	2/1/06	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM2.5-ST5-2/1/2006	Firehouse #10 (roof level)	2/1/06	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM2.5-ST10-2/1/2006	North Side Sidewalk Bridge	2/1/06	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM2.5-ST100-2/1/2006	Station 10 Field Duplicate	2/1/06	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM2.5-ST11-2/1/2006	90 Trinity Place (roof level)	2/1/06	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM2.5-ST12-2/1/2006	110 Greenwich Street (roof level)	2/1/06	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM2.5-ST13-2/1/2006	Marriott Hotel, 38th Floor (roof level)	2/1/06	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM2.5-ST14-2/1/2006	West Face - South end at corner (scaffolding level)	2/1/06	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM2.5-ST15-2/1/2006	South Face - East end at corner (scaffolding level)	2/1/06	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST16-2/1/2006	East Face - North end at corner (scaffolding level)	2/1/06	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM2.5-ST17-2/1/2006	North Face - West end at corner (scaffolding level)	2/1/06	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM2.5-ST1-2/2/2006	Southwest Area (sidewalk bridge level)	2/2/06	1440	Particulate	Direct Read	Met One E-BAM	33	No	No	
PM2.5-ST2-2/2/2006	Southeast Area (sidewalk bridge level)	2/2/06	1440	Particulate	Direct Read	Met One E-BAM	30	No	No	
PM2.5-ST4-2/2/2006	Northwest Area (street-level)	2/2/06	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM2.5-ST5-2/2/2006	Firehouse #10 (roof level)	2/2/06	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM2.5-ST10-2/2/2006	North Side Sidewalk Bridge	2/2/06	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM2.5-ST100-2/2/2006	Station 10 Field Duplicate	2/2/06	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM2.5-ST11-2/2/2006	90 Trinity Place (roof level)	2/2/06	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM2.5-ST12-2/2/2006	110 Greenwich Street (roof level)	2/2/06	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM2.5-ST13-2/2/2006	Marriott Hotel, 38th Floor (roof level)	2/2/06	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM2.5-ST14-2/2/2006	West Face - South end at corner (scaffolding level)	2/2/06	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM2.5-ST15-2/2/2006	South Face - East end at corner (scaffolding level)	2/2/06	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM2.5-ST16-2/2/2006	East Face - North end at corner (scaffolding level)	2/2/06	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM2.5-ST17-2/2/2006	North Face - West end at corner (scaffolding level)	2/2/06	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	