

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM2.5 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
							40			
							65			
Target Air Quality Levels										
EPA Site Specific Trigger Levels										
PM2.5-ST1-2/13/2006	Southwest Area (sidewalk bridge level)	2/13/06	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST2-2/13/2006	Southeast Area (sidewalk bridge level)	2/13/06	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	
PM2.5-ST4-2/13/2006	Northwest Area (street-level)	2/13/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM2.5-ST5-2/13/2006	Firehouse #10 (roof level)	2/13/06	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM2.5-ST10-2/13/2006	North Side Sidewalk Bridge	2/13/06	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST100-2/13/2006	Station 10 Field Duplicate	2/13/06	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM2.5-ST11-2/13/2006	90 Trinity Place (roof level)	2/13/06	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM2.5-ST12-2/13/2006	110 Greenwich Street (roof level)	2/13/06	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM2.5-ST13-2/13/2006	Marriott Hotel, 38th Floor (roof level)	2/13/06	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM2.5-ST14-2/13/2006	West Face - South end at corner (scaffolding level)	2/13/06	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST15-2/13/2006	South Face - East end at corner (scaffolding level)	2/13/06	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM2.5-ST16-2/13/2006	East Face - North end at corner (scaffolding level)	2/13/06	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM2.5-ST17-2/13/2006	North Face - West end at corner (scaffolding level)	2/13/06	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST1-2/14/2006	Southwest Area (sidewalk bridge level)	2/14/06	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM2.5-ST2-2/14/2006	Southeast Area (sidewalk bridge level)	2/14/06	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM2.5-ST4-2/14/2006	Northwest Area (street-level)	2/14/06	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM2.5-ST5-2/14/2006	Firehouse #10 (roof level)	2/14/06	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM2.5-ST10-2/14/2006	North Side Sidewalk Bridge	2/14/06	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM2.5-ST100-2/14/2006	Station 10 Field Duplicate	2/14/06	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM2.5-ST11-2/14/2006	90 Trinity Place (roof level)	2/14/06	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM2.5-ST12-2/14/2006	110 Greenwich Street (roof level)	2/14/06	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM2.5-ST13-2/14/2006	Marriott Hotel, 38th Floor (roof level)	2/14/06	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM2.5-ST14-2/14/2006	West Face - South end at corner (scaffolding level)	2/14/06	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM2.5-ST15-2/14/2006	South Face - East end at corner (scaffolding level)	2/14/06	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM2.5-ST16-2/14/2006	East Face - North end at corner (scaffolding level)	2/14/06	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM2.5-ST17-2/14/2006	North Face - West end at corner (scaffolding level)	2/14/06	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	