

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM2.5 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels							40			
EPA Site Specific Trigger Levels							65			
PM2.5-ST1-3/31/2006	Southwest Area (sidewalk bridge level)	3/31/06	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM2.5-ST2-3/31/2006	Southeast Area (sidewalk bridge level)	3/31/06	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM2.5-ST4-3/31/2006	Northwest Area (street-level)	3/31/06	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM2.5-ST5-3/31/2006	Firehouse #10 (roof level)	3/31/06	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM2.5-ST10-3/31/2006	North Side Sidewalk Bridge	3/31/06	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM2.5-ST100-3/31/2006	Station 10 Field Duplicate	3/31/06	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM2.5-ST11-3/31/2006	90 Trinity Place (roof level)	3/31/06	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM2.5-ST12-3/31/2006	110 Greenwich Street (roof level)	3/31/06	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM2.5-ST13-3/31/2006	Marriott Hotel, 38th Floor (roof level)	3/31/06	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM2.5-ST14-3/31/2006	West Face - South end at corner (scaffolding level)	3/31/06	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM2.5-ST15-3/31/2006	South Face - East end at corner (scaffolding level)	3/31/06	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM2.5-ST16-3/31/2006	East Face - North end at corner (scaffolding level)	3/31/06	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM2.5-ST17-3/31/2006	North Face - West end at corner (scaffolding level)	3/31/06	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM2.5-ST1-4/1/2006	Southwest Area (sidewalk bridge level)	4/1/06	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM2.5-ST2-4/1/2006	Southeast Area (sidewalk bridge level)	4/1/06	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM2.5-ST4-4/1/2006	Northwest Area (street-level)	4/1/06	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM2.5-ST5-4/1/2006	Firehouse #10 (roof level)	4/1/06	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM2.5-ST10-4/1/2006	North Side Sidewalk Bridge	4/1/06	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST100-4/1/2006	Station 10 Field Duplicate	4/1/06	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST11-4/1/2006	90 Trinity Place (roof level)	4/1/06	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST12-4/1/2006	110 Greenwich Street (roof level)	4/1/06	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST13-4/1/2006	Marriott Hotel, 38th Floor (roof level)	4/1/06	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM2.5-ST14-4/1/2006	West Face - South end at corner (scaffolding level)	4/1/06	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM2.5-ST15-4/1/2006	South Face - East end at corner (scaffolding level)	4/1/06	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM2.5-ST16-4/1/2006	East Face - North end at corner (scaffolding level)	4/1/06	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST17-4/1/2006	North Face - West end at corner (scaffolding level)	4/1/06	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST1-4/2/2006	Southwest Area (sidewalk bridge level)	4/2/06	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM2.5-ST2-4/2/2006	Southeast Area (sidewalk bridge level)	4/2/06	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM2.5-ST4-4/2/2006	Northwest Area (street-level)	4/2/06	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	
PM2.5-ST5-4/2/2006	Firehouse #10 (roof level)	4/2/06	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM2.5-ST10-4/2/2006	North Side Sidewalk Bridge	4/2/06	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	
PM2.5-ST100-4/2/2006	Station 10 Field Duplicate	4/2/06	1440	Particulate	Direct Read	Met One E-BAM	4	No	No	
PM2.5-ST11-4/2/2006	90 Trinity Place (roof level)	4/2/06	1440	Particulate	Direct Read	Met One E-BAM	4	No	No	
PM2.5-ST12-4/2/2006	110 Greenwich Street (roof level)	4/2/06	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	
PM2.5-ST13-4/2/2006	Marriott Hotel, 38th Floor (roof level)	4/2/06	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM2.5-ST14-4/2/2006	West Face - South end at corner (scaffolding level)	4/2/06	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM2.5-ST15-4/2/2006	South Face - East end at corner (scaffolding level)	4/2/06	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM2.5-ST16-4/2/2006	East Face - North end at corner (scaffolding level)	4/2/06	1440	Particulate	Direct Read	Met One E-BAM	4	No	No	
PM2.5-ST17-4/2/2006	North Face - West end at corner (scaffolding level)	4/2/06	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	