

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM2.5 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels							40			
EPA Site Specific Trigger Levels							65			
PM2.5-ST1-4/14/2006	Southwest Area (sidewalk bridge level)	4/14/06	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM2.5-ST2-4/14/2006	Southeast Area (sidewalk bridge level)	4/14/06	1440	Particulate	Direct Read	Met One E-BAM	30	No	No	
PM2.5-ST4-4/14/2006	Northwest Area (street-level)	4/14/06	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM2.5-ST5-4/14/2006	Firehouse #10 (roof level)	4/14/06	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM2.5-ST10-4/14/2006	North Side Sidewalk Bridge	4/14/06	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM2.5-ST100-4/14/2006	Station 10 Field Duplicate	4/14/06	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM2.5-ST11-4/14/2006	90 Trinity Place (roof level)	4/14/06	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM2.5-ST12-4/14/2006	110 Greenwich Street (roof level)	4/14/06	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM2.5-ST13-4/14/2006	Marriott Hotel, 38th Floor (roof level)	4/14/06	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM2.5-ST14-4/14/2006	West Face - South end at corner (scaffolding level)	4/14/06	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM2.5-ST15-4/14/2006	South Face - East end at corner (scaffolding level)	4/14/06	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM2.5-ST16-4/14/2006	East Face - North end at corner (scaffolding level)	4/14/06	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM2.5-ST17-4/14/2006	North Face - West end at corner (scaffolding level)	4/14/06	1440	Particulate	Direct Read	Met One E-BAM	31	No	No	
PM2.5-ST1-4/15/2006	Southwest Area (sidewalk bridge level)	4/15/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM2.5-ST2-4/15/2006	Southeast Area (sidewalk bridge level)	4/15/06	1440	Particulate	Direct Read	Met One E-BAM	36	No	No	
PM2.5-ST4-4/15/2006	Northwest Area (street-level)	4/15/06	1440	Particulate	Direct Read	Met One E-BAM	30	No	No	
PM2.5-ST5-4/15/2006	Firehouse #10 (roof level)	4/15/06	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM2.5-ST10-4/15/2006	North Side Sidewalk Bridge	4/15/06	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM2.5-ST100-4/15/2006	Station 10 Field Duplicate	4/15/06	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM2.5-ST11-4/15/2006	90 Trinity Place (roof level)	4/15/06	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM2.5-ST12-4/15/2006	110 Greenwich Street (roof level)	4/15/06	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM2.5-ST13-4/15/2006	Marriott Hotel, 38th Floor (roof level)	4/15/06	1440	Particulate	Direct Read	Met One E-BAM	33	No	No	
PM2.5-ST14-4/15/2006	West Face - South end at corner (scaffolding level)	4/15/06	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM2.5-ST15-4/15/2006	South Face - East end at corner (scaffolding level)	4/15/06	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM2.5-ST16-4/15/2006	East Face - North end at corner (scaffolding level)	4/15/06	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM2.5-ST17-4/15/2006	North Face - West end at corner (scaffolding level)	4/15/06	1440	Particulate	Direct Read	Met One E-BAM	37	No	No	
PM2.5-ST1-4/16/2006	Southwest Area (sidewalk bridge level)	4/16/06	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM2.5-ST2-4/16/2006	Southeast Area (sidewalk bridge level)	4/16/06	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM2.5-ST4-4/16/2006	Northwest Area (street-level)	4/16/06	1440	Particulate	Direct Read	Met One E-BAM	4	No	No	
PM2.5-ST5-4/16/2006	Firehouse #10 (roof level)	4/16/06	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM2.5-ST10-4/16/2006	North Side Sidewalk Bridge	4/16/06	1440	Particulate	Direct Read	Met One E-BAM	4	No	No	
PM2.5-ST100-4/16/2006	Station 10 Field Duplicate	4/16/06	1440	Particulate	Direct Read	Met One E-BAM	4	No	No	
PM2.5-ST11-4/16/2006	90 Trinity Place (roof level)	4/16/06	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	
PM2.5-ST12-4/16/2006	110 Greenwich Street (roof level)	4/16/06	1440	Particulate	Direct Read	Met One E-BAM	4	No	No	
PM2.5-ST13-4/16/2006	Marriott Hotel, 38th Floor (roof level)	4/16/06	1440	Particulate	Direct Read	Met One E-BAM	3	No	No	
PM2.5-ST14-4/16/2006	West Face - South end at corner (scaffolding level)	4/16/06	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM2.5-ST15-4/16/2006	South Face - East end at corner (scaffolding level)	4/16/06	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM2.5-ST16-4/16/2006	East Face - North end at corner (scaffolding level)	4/16/06	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	
PM2.5-ST17-4/16/2006	North Face - West end at corner (scaffolding level)	4/16/06	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	