

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM2.5 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels							40			
EPA Site Specific Trigger Levels							65			
PM2.5-ST2-9/8/2009	Southeast Area (sidewalk bridge level)	9/8/09	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM2.5-ST4-9/8/2009	Northwest Area (street-level)	9/8/09	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM2.5-ST5-9/8/2009	Firehouse #10 (roof level)	9/8/09	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST10-9/8/2009	North Side Sidewalk Bridge	9/8/09	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM2.5-ST100-9/8/2009	Station 10 Field Duplicate	9/8/09	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST11-9/8/2009	90 Trinity Place (roof level)	9/8/09	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM2.5-ST12-9/8/2009	110 Greenwich Street (roof level)	9/8/09	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM2.5-ST13-9/8/2009	Marriott Hotel, 38th Floor (roof level)	9/8/09	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	

Note:

1. The PM2.5 reading from Station 1 (Southwest Area [sidewalk bridge level]) on September 8, 2009 was not available on account of instrument malfunction.