

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM2.5 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
							40			
							65			
Target Air Quality Levels										
EPA Site Specific Trigger Levels										
PM2.5-ST1-9/25/2006	Southwest Area (sidewalk bridge level)	9/25/06	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM2.5-ST2-9/25/2006	Southeast Area (sidewalk bridge level)	9/25/06	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST4-9/25/2006	Northwest Area (street-level)	9/25/06	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM2.5-ST5-9/25/2006	Firehouse #10 (roof level)	9/25/06	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM2.5-ST10-9/25/2006	North Side Sidewalk Bridge	9/25/06	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM2.5-ST100-9/25/2006	Station 10 Field Duplicate	9/25/06	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM2.5-ST11-9/25/2006	90 Trinity Place (roof level)	9/25/06	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST12-9/25/2006	110 Greenwich Street (roof level)	9/25/06	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM2.5-ST13-9/25/2006	Marriott Hotel, 38th Floor (roof level)	9/25/06	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM2.5-ST14-9/25/2006	West Face - South end at corner (scaffolding level)	9/25/06	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM2.5-ST15-9/25/2006	South Face - East end at corner (scaffolding level)	9/25/06	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST16-9/25/2006	East Face - North end at corner (scaffolding level)	9/25/06	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM2.5-ST17-9/25/2006	North Face - West end at corner (scaffolding level)	9/25/06	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM2.5-ST1-9/26/2006	Southwest Area (sidewalk bridge level)	9/26/06	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST2-9/26/2006	Southeast Area (sidewalk bridge level)	9/26/06	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM2.5-ST4-9/26/2006	Northwest Area (street-level)	9/26/06	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM2.5-ST5-9/26/2006	Firehouse #10 (roof level)	9/26/06	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST10-9/26/2006	North Side Sidewalk Bridge	9/26/06	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM2.5-ST100-9/26/2006	Station 10 Field Duplicate	9/26/06	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM2.5-ST11-9/26/2006	90 Trinity Place (roof level)	9/26/06	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM2.5-ST12-9/26/2006	110 Greenwich Street (roof level)	9/26/06	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM2.5-ST13-9/26/2006	Marriott Hotel, 38th Floor (roof level)	9/26/06	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM2.5-ST14-9/26/2006	West Face - South end at corner (scaffolding level)	9/26/06	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM2.5-ST15-9/26/2006	South Face - East end at corner (scaffolding level)	9/26/06	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST16-9/26/2006	East Face - North end at corner (scaffolding level)	9/26/06	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM2.5-ST17-9/26/2006	North Face - West end at corner (scaffolding level)	9/26/06	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	