

| TRC Field Sample No. | Sample No. | Sampling Location | Collection Start Date | Sample Volume (m ³) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Dioxin TEQ Concentration (pg/m3) | Exceeds Target Air Quality Levels | Exceeds EPA Site Specific Trigger Levels | Comments |
|----------------------------------|----------------|----------------------------|-----------------------|---------------------------------|---------|-------------------|-----|-------------------------|----------------------------------|-----------------------------------|--|----------|
| Target Air Quality Levels | | | | | | | | | 0.25 | | | |
| EPA Site Specific Trigger Levels | | | | | | | | | 25 | | | |
| Dioxins/Furans-ST5-07/31/07 | P8182_5119_005 | Firehouse #10 (roof level) | 7/31/07 | 346 | Dioxin | TO-9A | AP | 8/3/07 | 0.0285 | No | No | |