

| TRC Field Sample No. | Sample No. | Sampling Location | Collection Start Date | Sample Volume (m ³) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Dioxin TEQ Concentration (pg/m3) | Exceeds Target Air Quality Levels | Exceeds EPA Site Specific Trigger Levels | Comments |
|---|----------------|---------------------------------|-----------------------|---------------------------------|---------|-------------------|-----|-------------------------|----------------------------------|-----------------------------------|--|----------|
| Target Air Quality Levels | | | | | | | | | 0.25 | | | |
| EPA Site Specific Trigger Levels | | | | | | | | | 25 | | | |
| Dioxins/Furans-ST20-8/17/10 | P2566_8071_006 | Northeast Area, Sidewalk Bridge | 8/17/10 | 395 | Dioxin | TO-9A | AP | 8/19/10 | 0.0157 | No | No | |
| Dioxins/Furans-ST200-8/17/10 | P2566_8071_009 | Station 20 Field Duplicate | 8/17/10 | 377 | Dioxin | TO-9A | AP | 8/19/10 | 0.0165 | No | No | |