TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Dioxin TEQ Concentration (pg/m3)	Exceeds Target	Exceeds EPA	
	0.25	Air Quality	Site Specific	Comments								
	25	Levels	Trigger Levels									
Dioxins/Furans-ST1-12/17/08	P9977_6455_002 S	Southwest Area (sidewalk bridge level)	12/17/08	337	Dioxin	TO-9A	AP	12/19/2008	0.02	No	No	
Dioxins/Furans-ST10-12/17/08	P9977_6455_006 N	lorth Side Sidewalk Bridge	12/17/08	328	Dioxin	TO-9A	AP	12/19/2008	0.0229	No	No	
Dioxins/Furans-ST100-12/17/08	P9977_6455_014 S	Station 10 Field Duplicate	12/17/08	332	Dioxin	TO-9A	AP	12/19/2008	0.0208	No	No	