TRC Field Sample No. Sample No. Sample	pling Location C	Collection Start Date	Sample Volume (m3)	Analyte	Analytical Meth	d Lab	Lab Sample Receipt Date	Antimony Concentration (ng/m3)	Barium Concentration (ng/m3)	Bervllium Concentration (ng/m3)	Cadmium Concentration (ng/m3)	Chromium (Total) Concentration (ng/m3)	Copper Concentration (ng/m3)	Lead Concentration (ng/m3	) Manganese Concentration (ng/m3)	Nickel Concentration (ng/m3)	Zinc Concentration (ng/m3	Exceeds Target	Exceeds EPA	
Target Air Quality Levels								5,000	5,000	20	40	600	10,000	1,500	500	200	16,000		Site Specific	
		Site Specific Trigger Le	evels					14,000	5,000	200	2,000	600	100,000	5,000	500	28,000	160,000	Levels	Trigger Levels	
METALS-ST5-8/27/07 G7H290201001 Firehouse #10 (roof lev		8/27/07	1756.9	Metals	6020	STL-SAC	8/29/07	4.9	< 68.3	< 0.68	< 0.68	7.8	90.3	39.9	44.2	18.6	209	No	No	
METALS-ST10-8/27/07 G7H290201002 North Side Sidewalk Br		8/27/07	1776.9	Metals	6020	STL-SAC	8/29/07	4.5	< 67.5	< 0.68	< 0.68	< 6.8	246	15.1	33.1	16.8	90.9	No	No	
METALS-ST11-8/27/07 G7H290201003 90 Trinity Place (roof le	level'	8/27/07	1813.8	Metals	6020	STL-SAC	8/29/07	4.1	< 66.2	< 0.66	< 0.66	< 6.6	208	11.2	20.1	13.2	65.4	No	No	
METALS-ST12-8/27/07 G7H290201004 110 Greenwich Street (		8/27/07	1822.4	Metals	6020	STL-SAC	8/29/07	4.0	< 65.8	< 0.66	< 0.66	< 6.6	46.7	11.6	22.2	13.5	78.2	No	No	
METALS-ST13-8/27/07 G7H290201005 Marriott Hotel, 38th Flo	oor (roof level	8/27/07	1837.2	Metals	6020	STL-SAC	8/29/07	3.9	< 65.3	< 0.65	< 0.65	< 6.5	184	10.0	15.7	12.8	52.8	No	No	
METALS-ST14-8/27/07 G7H290201006 West Face - South end	d at corner (scaffolding level	8/27/07	1814.1	Metals	6020	STL-SAC	8/29/07	2.9	< 66.1	< 0.66	< 0.66	< 6.6	173	9.0	17.4	6.7	76.5	No	No	
METALS-ST16-8/27/07 G7H290201007 East Face - North end a	at corner (scaffolding level	8/27/07	1753	Metals	6020	STL-SAC	8/29/07	2.9	< 68.4	< 0.68	< 0.68	< 6.8	200	8.8	21.7	6.0	79.7	No	No	
METALS-ST17-8/27/07 G7H290201008 North Face - West end	d at corner (scaffolding level	8/27/07	1821.2	Metals	6020	STL-SAC	8/29/07	4.0	< 65.9	< 0.66	< 0.66	< 6.6	554	11.4	26.3	7.5	139	No	No	

Note:
1. Metals samples at Station 1 (Southwest Area [sidewalk bridge level]), Station 2 (Southeast Area [sidewalk bridge level]), and Station 4 (Northwest Area [street-level]) on August 27, 2007 were not collected. The stations were not accessible on account of a fine at 130 Lberry Street that caused unsafe conditions in the vicinity of the stations.
2. Metals sample at Station 15 (South Face - East end at corner [scaffolding level]) on August 27, 2007 was not available for analysis on account of pump failure.

130 Liberty Street Deconstruction Project Page 1 of 1