

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									10			
									10			
SILICA-ST1-1/6/06	040600394-0001	Southwest Area (sidewalk bridge level)	1/6/06	3.62	Silica	NIOSH 7500 XRD	EMSL	1/9/06	< 1	No	No	
SILICA-ST2-1/6/06	040600394-0002	Southeast Area (sidewalk bridge level)	1/6/06	3.58	Silica	NIOSH 7500 XRD	EMSL	1/9/06	< 1	No	No	
SILICA-ST4-1/6/06	040600394-0003	Northwest Area (street-level)	1/6/06	3.61	Silica	NIOSH 7500 XRD	EMSL	1/9/06	< 1	No	No	
SILICA-ST5-1/6/06	040600394-0004	Firehouse #10 (roof level)	1/6/06	3.61	Silica	NIOSH 7500 XRD	EMSL	1/9/06	2	No	No	
SILICA-ST10-1/6/06	040600394-0005	North Side Sidewalk Bridge	1/6/06	3.57	Silica	NIOSH 7500 XRD	EMSL	1/9/06	< 1	No	No	
SILICA-ST100-1/6/06	040600394-0013	Station 10 Field Duplicate	1/6/06	3.6	Silica	NIOSH 7500 XRD	EMSL	1/9/06	< 1	No	No	
SILICA-ST11-1/6/06	040600394-0006	90 Trinity Place (roof level)	1/6/06	3.69	Silica	NIOSH 7500 XRD	EMSL	1/9/06	< 1	No	No	
SILICA-ST12-1/6/06	040600394-0007	110 Greenwich Street (roof level)	1/6/06	3.87	Silica	NIOSH 7500 XRD	EMSL	1/9/06	< 1	No	No	
SILICA-ST13-1/6/06	040600394-0008	Marriott Hotel, 38th Floor (roof level)	1/6/06	3.78	Silica	NIOSH 7500 XRD	EMSL	1/9/06	< 1	No	No	
SILICA-ST14-1/6/06	040600394-0009	West Face - South end at corner (scaffolding level)	1/6/06	3.37	Silica	NIOSH 7500 XRD	EMSL	1/9/06	< 1	No	No	
SILICA-ST15-1/6/06	040600394-0010	South Face - East end at corner (scaffolding level)	1/6/06	3.4	Silica	NIOSH 7500 XRD	EMSL	1/9/06	< 1	No	No	
SILICA-ST16-1/6/06	040600394-0011	East Face - North end at corner (scaffolding level)	1/6/06	3.4	Silica	NIOSH 7500 XRD	EMSL	1/9/06	< 1	No	No	
SILICA-ST17-1/6/06	040600394-0012	North Face - West end at corner (scaffolding level)	1/6/06	3.37	Silica	NIOSH 7500 XRD	EMSL	1/9/06	< 1	No	No	
SILICA-ST1-1/7/06	040600396-0001	Southwest Area (sidewalk bridge level)	1/7/06	3.54	Silica	NIOSH 7500 XRD	EMSL	1/9/06	< 1	No	No	
SILICA-ST2-1/7/06	040600396-0002	Southeast Area (sidewalk bridge level)	1/7/06	3.53	Silica	NIOSH 7500 XRD	EMSL	1/9/06	< 1	No	No	
SILICA-ST4-1/7/06	040600396-0003	Northwest Area (street-level)	1/7/06	3.52	Silica	NIOSH 7500 XRD	EMSL	1/9/06	< 1	No	No	
SILICA-ST5-1/7/06	040600396-0004	Firehouse #10 (roof level)	1/7/06	3.57	Silica	NIOSH 7500 XRD	EMSL	1/9/06	< 1	No	No	
SILICA-ST10-1/7/06	040600396-0005	North Side Sidewalk Bridge	1/7/06	3.52	Silica	NIOSH 7500 XRD	EMSL	1/9/06	< 1	No	No	
SILICA-ST11-1/7/06	040600396-0006	90 Trinity Place (roof level)	1/7/06	3.58	Silica	NIOSH 7500 XRD	EMSL	1/9/06	< 1	No	No	
SILICA-ST12-1/7/06	040600396-0007	110 Greenwich Street (roof level)	1/7/06	3.29	Silica	NIOSH 7500 XRD	EMSL	1/9/06	< 6	No	No	
SILICA-ST13-1/7/06	040600396-0008	Marriott Hotel, 38th Floor (roof level)	1/7/06	3.24	Silica	NIOSH 7500 XRD	EMSL	1/9/06	< 2	No	No	
SILICA-ST14-1/7/06	040600396-0009	West Face - South end at corner (scaffolding level)	1/7/06	3.53	Silica	NIOSH 7500 XRD	EMSL	1/9/06	< 1	No	No	
SILICA-ST15-1/7/06	040600396-0010	South Face - East end at corner (scaffolding level)	1/7/06	3.51	Silica	NIOSH 7500 XRD	EMSL	1/9/06	< 1	No	No	
SILICA-ST16-1/7/06	040600396-0011	East Face - North end at corner (scaffolding level)	1/7/06	3.49	Silica	NIOSH 7500 XRD	EMSL	1/9/06	< 1	No	No	
SILICA-ST17-1/7/06	040600396-0012	North Face - West end at corner (scaffolding level)	1/7/06	3.51	Silica	NIOSH 7500 XRD	EMSL	1/9/06	< 1	No	No	
SILICA-ST1-1/8/06	040600394-0001	Southwest Area (sidewalk bridge level)	1/8/06	3.65	Silica	NIOSH 7500 XRD	EMSL	1/10/06	< 1	No	No	
SILICA-ST2-1/8/06	040600394-0002	Southeast Area (sidewalk bridge level)	1/8/06	3.65	Silica	NIOSH 7500 XRD	EMSL	1/10/06	< 1	No	No	
SILICA-ST4-1/8/06	040600394-0003	Northwest Area (street-level)	1/8/06	3.67	Silica	NIOSH 7500 XRD	EMSL	1/10/06	< 1	No	No	
SILICA-ST5-1/8/06	040600394-0004	Firehouse #10 (roof level)	1/8/06	3.56	Silica	NIOSH 7500 XRD	EMSL	1/10/06	< 1	No	No	
SILICA-ST10-1/8/06	040600394-0005	North Side Sidewalk Bridge	1/8/06	3.68	Silica	NIOSH 7500 XRD	EMSL	1/10/06	< 1	No	No	
SILICA-ST11-1/8/06	040600394-0006	90 Trinity Place (roof level)	1/8/06	3.49	Silica	NIOSH 7500 XRD	EMSL	1/10/06	< 1	No	No	
SILICA-ST12-1/8/06	040600394-0007	110 Greenwich Street (roof level)	1/8/06	3.54	Silica	NIOSH 7500 XRD	EMSL	1/10/06	< 1	No	No	
SILICA-ST13-1/8/06	040600394-0008	Marriott Hotel, 38th Floor (roof level)	1/8/06	3.61	Silica	NIOSH 7500 XRD	EMSL	1/10/06	< 1	No	No	
SILICA-ST14-1/8/06	040600394-0009	West Face - South end at corner (scaffolding level)	1/8/06	3.79	Silica	NIOSH 7500 XRD	EMSL	1/10/06	< 1	No	No	
SILICA-ST15-1/8/06	040600394-0010	South Face - East end at corner (scaffolding level)	1/8/06	3.74	Silica	NIOSH 7500 XRD	EMSL	1/10/06	< 1	No	No	
SILICA-ST16-1/8/06	040600394-0011	East Face - North end at corner (scaffolding level)	1/8/06	3.75	Silica	NIOSH 7500 XRD	EMSL	1/10/06	< 1	No	No	
SILICA-ST17-1/8/06	040600394-0012	North Face - West end at corner (scaffolding level)	1/8/06	3.77	Silica	NIOSH 7500 XRD	EMSL	1/10/06	< 1	No	No	