

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target	Exceeds EPA	Comments
									10	Air Quality Levels	Site Specific Trigger Levels	
Target Air Quality Levels									10			
EPA Site Specific Trigger Levels												
SILICA-ST1-1/8/08	040800527-0001	Southwest Area (sidewalk bridge level)	1/8/08	3.52	Silica	NIOSH 7500 XRD	EMSL	1/9/08	< 1	No	No	
SILICA-ST2-1/8/08	040800527-0002	Southeast Area (sidewalk bridge level)	1/8/08	3.53	Silica	NIOSH 7500 XRD	EMSL	1/9/08	< 1	No	No	
SILICA-ST4-1/8/08	040800527-0003	Northwest Area (street-level)	1/8/08	3.56	Silica	NIOSH 7500 XRD	EMSL	1/9/08	< 1	No	No	
SILICA-ST5-1/8/08	040800527-0004	Firehouse #10 (roof level)	1/8/08	3.52	Silica	NIOSH 7500 XRD	EMSL	1/9/08	< 1	No	No	
SILICA-ST10-1/8/08	040800527-0005	North Side Sidewalk Bridge	1/8/08	3.56	Silica	NIOSH 7500 XRD	EMSL	1/9/08	< 1	No	No	
SILICA-ST11-1/8/08	040800527-0006	90 Trinity Place (roof level)	1/8/08	3.54	Silica	NIOSH 7500 XRD	EMSL	1/9/08	< 1	No	No	
SILICA-ST12-1/8/08	040800527-0007	110 Greenwich Street (roof level)	1/8/08	3.58	Silica	NIOSH 7500 XRD	EMSL	1/9/08	< 1	No	No	
SILICA-ST13-1/8/08	040800527-0008	Marriott Hotel, 38th Floor (roof level)	1/8/08	3.72	Silica	NIOSH 7500 XRD	EMSL	1/9/08	< 1	No	No	
SILICA-ST14(15th) -1/8/08	040800527-0009	West Face - South end at corner (scaffolding level)	1/8/08	3.38	Silica	NIOSH 7500 XRD	EMSL	1/9/08	< 1	No	No	
SILICA-ST15(15th) -1/8/08	040800527-0010	South Face - East end at corner (scaffolding level)	1/8/08	3.52	Silica	NIOSH 7500 XRD	EMSL	1/9/08	< 1	No	No	
SILICA-ST16(15th) -1/8/08	040800527-0011	East Face - North end at corner (scaffolding level)	1/8/08	3.54	Silica	NIOSH 7500 XRD	EMSL	1/9/08	< 1	No	No	
SILICA-ST17(15th) -1/8/08	040800527-0012	North Face - West end at corner (scaffolding level)	1/8/08	3.53	Silica	NIOSH 7500 XRD	EMSL	1/9/08	< 1	No	No	
SILICA-ST1-1/9/08	040800653-0001	Southwest Area (sidewalk bridge level)	1/9/08	3.63	Silica	NIOSH 7500 XRD	EMSL	1/10/08	< 1	No	No	
SILICA-ST2-1/9/08	040800653-0002	Southeast Area (sidewalk bridge level)	1/9/08	3.58	Silica	NIOSH 7500 XRD	EMSL	1/10/08	< 1	No	No	
SILICA-ST4-1/9/08	040800653-0003	Northwest Area (street-level)	1/9/08	3.63	Silica	NIOSH 7500 XRD	EMSL	1/10/08	< 1	No	No	
SILICA-ST5-1/9/08	040800653-0004	Firehouse #10 (roof level)	1/9/08	3.42	Silica	NIOSH 7500 XRD	EMSL	1/10/08	< 1	No	No	
SILICA-ST10-1/9/08	040800653-0005	North Side Sidewalk Bridge	1/9/08	3.54	Silica	NIOSH 7500 XRD	EMSL	1/10/08	< 1	No	No	
SILICA-ST11-1/9/08	040800653-0006	90 Trinity Place (roof level)	1/9/08	3.53	Silica	NIOSH 7500 XRD	EMSL	1/10/08	< 1	No	No	
SILICA-ST12-1/9/08	040800653-0007	110 Greenwich Street (roof level)	1/9/08	3.59	Silica	NIOSH 7500 XRD	EMSL	1/10/08	< 1	No	No	
SILICA-ST13-1/9/08	040800653-0008	Marriott Hotel, 38th Floor (roof level)	1/9/08	3.46	Silica	NIOSH 7500 XRD	EMSL	1/10/08	< 1	No	No	
SILICA-ST14(15th) -1/9/08	040800653-0009	West Face - South end at corner (scaffolding level)	1/9/08	3.46	Silica	NIOSH 7500 XRD	EMSL	1/10/08	< 1	No	No	
SILICA-ST15(15th) -1/9/08	040800653-0010	South Face - East end at corner (scaffolding level)	1/9/08	3.53	Silica	NIOSH 7500 XRD	EMSL	1/10/08	< 1	No	No	
SILICA-ST16(15th) -1/9/08	040800653-0011	East Face - North end at corner (scaffolding level)	1/9/08	3.52	Silica	NIOSH 7500 XRD	EMSL	1/10/08	< 1	No	No	
SILICA-ST17(15th) -1/9/08	040800653-0012	North Face - West end at corner (scaffolding level)	1/9/08	3.50	Silica	NIOSH 7500 XRD	EMSL	1/10/08	< 1	No	No	