

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									10			
									10			
SILICA-ST1-1/9/06	040600502-0001	Southwest Area (sidewalk bridge level)	1/9/06	3.58	Silica	NIOSH 7500 XRD	EMSL	1/10/06	< 1	No	No	
SILICA-ST2-1/9/06	040600502-0002	Southeast Area (sidewalk bridge level)	1/9/06	3.59	Silica	NIOSH 7500 XRD	EMSL	1/10/06	< 1	No	No	
SILICA-ST4-1/9/06	040600502-0003	Northwest Area (street-level)	1/9/06	3.63	Silica	NIOSH 7500 XRD	EMSL	1/10/06	< 1	No	No	
SILICA-ST5-1/9/06	040600502-0004	Firehouse #10 (roof level)	1/9/06	3.62	Silica	NIOSH 7500 XRD	EMSL	1/10/06	< 1	No	No	
SILICA-ST10-1/9/06	040600502-0005	North Side Sidewalk Bridge	1/9/06	3.63	Silica	NIOSH 7500 XRD	EMSL	1/10/06	< 1	No	No	
SILICA-ST11-1/9/06	040600502-0006	90 Trinity Place (roof level)	1/9/06	3.59	Silica	NIOSH 7500 XRD	EMSL	1/10/06	< 1	No	No	
SILICA-ST12-1/9/06	040600502-0007	110 Greenwich Street (roof level)	1/9/06	3.67	Silica	NIOSH 7500 XRD	EMSL	1/10/06	< 1	No	No	
SILICA-ST13-1/9/06	040600502-0008	Marriott Hotel, 38th Floor (roof level)	1/9/06	3.74	Silica	NIOSH 7500 XRD	EMSL	1/10/06	< 1	No	No	
SILICA-ST1-1/10/06	040600614-0001	Southwest Area (sidewalk bridge level)	1/10/06	3.51	Silica	NIOSH 7500 XRD	EMSL	1/11/06	< 1	No	No	
SILICA-ST2-1/10/06	040600614-0002	Southeast Area (sidewalk bridge level)	1/10/06	3.5	Silica	NIOSH 7500 XRD	EMSL	1/11/06	< 1	No	No	
SILICA-ST4-1/10/06	040600614-0003	Northwest Area (street-level)	1/10/06	3.5	Silica	NIOSH 7500 XRD	EMSL	1/11/06	< 1	No	No	
SILICA-ST5-1/10/06	040600614-0004	Firehouse #10 (roof level)	1/10/06	3.51	Silica	NIOSH 7500 XRD	EMSL	1/11/06	< 1	No	No	
SILICA-ST10-1/10/06	040600614-0005	North Side Sidewalk Bridge	1/10/06	3.51	Silica	NIOSH 7500 XRD	EMSL	1/11/06	< 1	No	No	
SILICA-ST11-1/10/06	040600614-0006	90 Trinity Place (roof level)	1/10/06	3.58	Silica	NIOSH 7500 XRD	EMSL	1/11/06	< 1	No	No	
SILICA-ST12-1/10/06	040600614-0007	110 Greenwich Street (roof level)	1/10/06	3.56	Silica	NIOSH 7500 XRD	EMSL	1/11/06	< 6	No	No	
SILICA-ST13-1/10/06	040600614-0008	Marriott Hotel, 38th Floor (roof level)	1/10/06	3.45	Silica	NIOSH 7500 XRD	EMSL	1/11/06	< 1	No	No	
SILICA-ST14-1/10/06	040600614-0009	West Face - South end at corner (scaffolding level)	1/10/06	3.57	Silica	NIOSH 7500 XRD	EMSL	1/11/06	< 1	No	No	
SILICA-ST15-1/10/06	040600614-0010	South Face - East end at corner (scaffolding level)	1/10/06	3.65	Silica	NIOSH 7500 XRD	EMSL	1/11/06	< 1	No	No	
SILICA-ST16-1/10/06	040600614-0011	East Face - North end at corner (scaffolding level)	1/10/06	3.66	Silica	NIOSH 7500 XRD	EMSL	1/11/06	< 1	No	No	
SILICA-ST17-1/10/06	040600614-0012	North Face - West end at corner (scaffolding level)	1/10/06	3.63	Silica	NIOSH 7500 XRD	EMSL	1/11/06	< 1	No	No	

Note:
1. On January 9, 2006, Stations 14 through 17 were moved from the 20th floor scaffolding level to the 30th floor scaffolding level and were temporarily disabled. No measurements were collected this day. No abatement activities took place on January 9, 2006. Work activities were limited to scaffolding erection.