

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									10			
									10			
SILICA-ST1-1/10/07	040700726-0001	Southwest Area (sidewalk bridge level)	1/10/07	3.72	Silica	NIOSH 7500 XRD	EMSL	1/11/07	< 1	No	No	
SILICA-ST2-1/10/07	040700726-0002	Southeast Area (sidewalk bridge level)	1/10/07	3.86	Silica	NIOSH 7500 XRD	EMSL	1/11/07	< 1	No	No	
SILICA-ST4-1/10/07	040700726-0003	Northwest Area (street-level)	1/10/07	3.62	Silica	NIOSH 7500 XRD	EMSL	1/11/07	< 1	No	No	
SILICA-ST5-1/10/07	040700726-0004	Firehouse #10 (roof level)	1/10/07	3.52	Silica	NIOSH 7500 XRD	EMSL	1/11/07	< 1	No	No	
SILICA-ST10-1/10/07	040700726-0005	North Side Sidewalk Bridge	1/10/07	3.59	Silica	NIOSH 7500 XRD	EMSL	1/11/07	< 1	No	No	
SILICA-ST11-1/10/07	040700726-0006	90 Trinity Place (roof level)	1/10/07	3.56	Silica	NIOSH 7500 XRD	EMSL	1/11/07	< 1	No	No	
SILICA-ST12-1/10/07	040700726-0007	110 Greenwich Street (roof level)	1/10/07	3.35	Silica	NIOSH 7500 XRD	EMSL	1/11/07	< 1	No	No	
SILICA-ST13-1/10/07	040700726-0008	Marriott Hotel, 38th Floor (roof level)	1/10/07	3.42	Silica	NIOSH 7500 XRD	EMSL	1/11/07	< 1	No	No	
SILICA-ST14-1/10/07	040700726-0009	West Face - South end at corner (scaffolding level)	1/10/07	3.57	Silica	NIOSH 7500 XRD	EMSL	1/11/07	< 1	No	No	
SILICA-ST15-1/10/07	040700726-0010	South Face - East end at corner (scaffolding level)	1/10/07	3.6	Silica	NIOSH 7500 XRD	EMSL	1/11/07	< 1	No	No	
SILICA-ST16-1/10/07	040700726-0011	East Face - North end at corner (scaffolding level)	1/10/07	3.59	Silica	NIOSH 7500 XRD	EMSL	1/11/07	< 1	No	No	
SILICA-ST17-1/10/07	040700726-0012	North Face - West end at corner (scaffolding level)	1/10/07	3.65	Silica	NIOSH 7500 XRD	EMSL	1/11/07	< 1	No	No	