

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target	Exceeds EPA	Comments
									<b>10</b>	<b>Air Quality Levels</b>	<b>Site Specific Trigger Levels</b>	
									<b>10</b>			
SILICA-ST1-1/26/09	040902477-0001	Southwest Area (sidewalk bridge level)	1/26/09	3.77	Silica	NIOSH 7500 XRD	EMSL	1/27/09	< 1	No	No	
SILICA-ST2-1/26/09	040902477-0002	Southeast Area (sidewalk bridge level)	1/26/09	3.67	Silica	NIOSH 7500 XRD	EMSL	1/27/09	< 1	No	No	
SILICA-ST4-1/26/09	040902477-0003	Northwest Area (street-level)	1/26/09	3.52	Silica	NIOSH 7500 XRD	EMSL	1/27/09	< 1	No	No	
SILICA-ST5-1/26/09	040902477-0004	Firehouse #10 (roof level)	1/26/09	3.67	Silica	NIOSH 7500 XRD	EMSL	1/27/09	1	No	No	
SILICA-ST10-1/26/09	040902477-0005	North Side Sidewalk Bridge	1/26/09	3.71	Silica	NIOSH 7500 XRD	EMSL	1/27/09	< 1	No	No	
SILICA-ST11-1/26/09	040902477-0006	90 Trinity Place (roof level)	1/26/09	3.6	Silica	NIOSH 7500 XRD	EMSL	1/27/09	< 1	No	No	
SILICA-ST12-1/26/09	040902477-0007	110 Greenwich Street (roof level)	1/26/09	3.58	Silica	NIOSH 7500 XRD	EMSL	1/27/09	< 1	No	No	
SILICA-ST13-1/26/09	040902477-0008	Marriott Hotel, 38th Floor (roof level)	1/26/09	3.59	Silica	NIOSH 7500 XRD	EMSL	1/27/09	< 1	No	No	
SILICA-ST14(15th)-1/26/09	040902477-0009	West Face - South end at corner (scaffolding level: 15th floor)	1/26/09	3.5	Silica	NIOSH 7500 XRD	EMSL	1/27/09	< 1	No	No	
SILICA-ST15(15th)-1/26/09	040902477-0010	South Face - East end at corner (scaffolding level: 15th floor)	1/26/09	3.46	Silica	NIOSH 7500 XRD	EMSL	1/27/09	< 1	No	No	
SILICA-ST16(15th)-1/26/09	040902477-0011	East Face - North end at corner (scaffolding level: 15th floor)	1/26/09	3.5	Silica	NIOSH 7500 XRD	EMSL	1/27/09	< 1	No	No	
SILICA-ST17(15th)-1/26/09	040902477-0012	North Face - West end at corner (scaffolding level: 15th floor)	1/26/09	3.53	Silica	NIOSH 7500 XRD	EMSL	1/27/09	3	No	No	