

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									10			
									10			
SILICA-ST1-1/31/07	040702171-0001	Southwest Area (sidewalk bridge level)	1/31/07	3.39	Silica	NIOSH 7500 XRD	EMSL	2/1/07	< 1	No	No	
SILICA-ST2-1/31/07	040702171-0002	Southeast Area (sidewalk bridge level)	1/31/07	3.49	Silica	NIOSH 7500 XRD	EMSL	2/1/07	< 1	No	No	
SILICA-ST4-1/31/07	040702171-0003	Northwest Area (street-level)	1/31/07	3.61	Silica	NIOSH 7500 XRD	EMSL	2/1/07	< 1	No	No	
SILICA-ST5-1/31/07	040702171-0004	Firehouse #10 (roof level)	1/31/07	3.59	Silica	NIOSH 7500 XRD	EMSL	2/1/07	< 6	No	No	
SILICA-ST10-1/31/07	040702171-0005	North Side Sidewalk Bridge	1/31/07	3.71	Silica	NIOSH 7500 XRD	EMSL	2/1/07	< 1	No	No	
SILICA-ST100-1/31/07	040702171-0013	Station 10 Field Duplicate	1/31/07	3.62	Silica	NIOSH 7500 XRD	EMSL	2/1/07	3	No	No	
SILICA-ST11-1/31/07	040702171-0006	90 Trinity Place (roof level)	1/31/07	3.57	Silica	NIOSH 7500 XRD	EMSL	2/1/07	3	No	No	
SILICA-ST12-1/31/07	040702171-0007	110 Greenwich Street (roof level)	1/31/07	3.35	Silica	NIOSH 7500 XRD	EMSL	2/1/07	< 1	No	No	
SILICA-ST13-1/31/07	040702171-0008	Marriott Hotel, 38th Floor (roof level)	1/31/07	3.63	Silica	NIOSH 7500 XRD	EMSL	2/1/07	< 1	No	No	
SILICA-ST14-1/31/07	040702171-0009	West Face - South end at corner (scaffolding level)	1/31/07	3.62	Silica	NIOSH 7500 XRD	EMSL	2/1/07	< 1	No	No	
SILICA-ST15-1/31/07	040702171-0010	South Face - East end at corner (scaffolding level)	1/31/07	3.61	Silica	NIOSH 7500 XRD	EMSL	2/1/07	2	No	No	
SILICA-ST16-1/31/07	040702171-0011	East Face - North end at corner (scaffolding level)	1/31/07	3.59	Silica	NIOSH 7500 XRD	EMSL	2/1/07	< 1	No	No	
SILICA-ST17-1/31/07	040702171-0012	North Face - West end at corner (scaffolding level)	1/31/07	3.55	Silica	NIOSH 7500 XRD	EMSL	2/1/07	< 1	No	No	
SILICA-ST1-2/1/07	040702256-0001	Southwest Area (sidewalk bridge level)	2/1/07	3.62	Silica	NIOSH 7500 XRD	EMSL	2/2/07	< 1	No	No	
SILICA-ST2-2/1/07	040702256-0002	Southeast Area (sidewalk bridge level)	2/1/07	3.62	Silica	NIOSH 7500 XRD	EMSL	2/2/07	< 1	No	No	
SILICA-ST4-2/1/07	040702256-0003	Northwest Area (street-level)	2/1/07	3.45	Silica	NIOSH 7500 XRD	EMSL	2/2/07	< 1	No	No	
SILICA-ST5-2/1/07	040702256-0004	Firehouse #10 (roof level)	2/1/07	3.59	Silica	NIOSH 7500 XRD	EMSL	2/2/07	< 1	No	No	
SILICA-ST10-2/1/07	040702256-0005	North Side Sidewalk Bridge	2/1/07	3.49	Silica	NIOSH 7500 XRD	EMSL	2/2/07	< 1	No	No	
SILICA-ST11-2/1/07	040702256-0006	90 Trinity Place (roof level)	2/1/07	3.57	Silica	NIOSH 7500 XRD	EMSL	2/2/07	< 1	No	No	
SILICA-ST12-2/1/07	040702256-0007	110 Greenwich Street (roof level)	2/1/07	3.64	Silica	NIOSH 7500 XRD	EMSL	2/2/07	< 1	No	No	
SILICA-ST13-2/1/07	040702256-0008	Marriott Hotel, 38th Floor (roof level)	2/1/07	3.61	Silica	NIOSH 7500 XRD	EMSL	2/2/07	< 1	No	No	
SILICA-ST14-2/1/07	040702256-0009	West Face - South end at corner (scaffolding level)	2/1/07	3.58	Silica	NIOSH 7500 XRD	EMSL	2/2/07	1	No	No	
SILICA-ST15-2/1/07	040702256-0010	South Face - East end at corner (scaffolding level)	2/1/07	3.55	Silica	NIOSH 7500 XRD	EMSL	2/2/07	< 1	No	No	
SILICA-ST16-2/1/07	040702256-0011	East Face - North end at corner (scaffolding level)	2/1/07	3.56	Silica	NIOSH 7500 XRD	EMSL	2/2/07	< 1	No	No	
SILICA-ST17-2/1/07	040702256-0012	North Face - West end at corner (scaffolding level)	2/1/07	3.58	Silica	NIOSH 7500 XRD	EMSL	2/2/07	< 1	No	No	