

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									10			
Target Air Quality Levels												
EPA Site Specific Trigger Levels									10			
SILICA-ST1-2/4/09	040903218-0001	Southwest Area (sidewalk bridge level)	2/4/09	3.73	Silica	NIOSH 7500 XRD	EMSL	2/5/09	< 1	No	No	
SILICA-ST2-2/4/09	040903218-0002	Southeast Area (sidewalk bridge level)	2/4/09	3.72	Silica	NIOSH 7500 XRD	EMSL	2/5/09	< 1	No	No	
SILICA-ST4-2/4/09	040903218-0003	Northwest Area (street-level)	2/4/09	3.7	Silica	NIOSH 7500 XRD	EMSL	2/5/09	< 1	No	No	
SILICA-ST5-2/4/09	040903218-0004	Firehouse #10 (roof level)	2/4/09	3.55	Silica	NIOSH 7500 XRD	EMSL	2/5/09	< 1	No	No	
SILICA-ST10-2/4/09	040903218-0005	North Side Sidewalk Bridge	2/4/09	3.31	Silica	NIOSH 7500 XRD	EMSL	2/5/09	< 1	No	No	
SILICA-ST11-2/4/09	040903218-0006	90 Trinity Place (roof level)	2/4/09	3.54	Silica	NIOSH 7500 XRD	EMSL	2/5/09	< 1	No	No	
SILICA-ST12-2/4/09	040903218-0007	110 Greenwich Street (roof level)	2/4/09	3.58	Silica	NIOSH 7500 XRD	EMSL	2/5/09	< 1	No	No	
SILICA-ST13-2/4/09	040903218-0008	Marriott Hotel, 38th Floor (roof level)	2/4/09	3.59	Silica	NIOSH 7500 XRD	EMSL	2/5/09	< 1	No	No	
SILICA-ST14(15th)-2/4/09	040903218-0009	West Face - South end at corner (scaffolding level: 15th floor)	2/4/09	3.57	Silica	NIOSH 7500 XRD	EMSL	2/5/09	< 1	No	No	
SILICA-ST15(15th)-2/4/09	040903218-0010	South Face - East end at corner (scaffolding level: 15th floor)	2/4/09	3.51	Silica	NIOSH 7500 XRD	EMSL	2/5/09	< 1	No	No	
SILICA-ST16(15th)-2/4/09	040903218-0011	East Face - North end at corner (scaffolding level: 15th floor)	2/4/09	3.65	Silica	NIOSH 7500 XRD	EMSL	2/5/09	< 1	No	No	
SILICA-ST17(15th)-2/4/09	040903218-0012	North Face - West end at corner (scaffolding level: 15th floor)	2/4/09	3.72	Silica	NIOSH 7500 XRD	EMSL	2/5/09	< 1	No	No	